





report date: 2024-03-28

#### General information

Make	JAGUAR
Model	S-TYPE V6 SPORT
Colour	Black
Year of manufacture	2006
Top speed	141 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	206 BHP
Max. torque	435 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	46.3 mpg
Consumption combined	35.3 mpg
CO2 emission	208 g/km
CO2 label	K



CarCheck.co.uk page 1/13



report date: 2024-03-28


### Internet history

#### Entry 2

Date 2022-01-28

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk


Entry 1

Date	2021-07-16

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-07-26
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	17
Total items failed	6

MOT #18	2023-07-27 15:58
MOT test number	977940519955
Result	✓ Passed
Next expiry date	2024-07-26

MOT #17	2022-03-16 11:06
MOT test number	873195983579
Result	✓ Passed
Advice Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c))	

MOT #16	2022-03-08 11:13
MOT test number	164438378406
Result	<b>X</b> Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Nearside Rear Service brake excessively binding (1.2.1 (f))	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #15** 2021-03-26 07:55

**MOT test number** 274317546696

**Result** ✓ Passed

**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #14 2021-03-24 17:33

MOT test number 248672168802

**Result** X Failed

**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

**MOT #13** 2019-09-30 11:14

MOT test number 499111089743

Result \( \sqrt{Passed} \)

**Advice** Offside Front h/lamp leveling device malfunctioning

Advice Front Brake disc worn, pitted or scored, but not seriously weakened upper lip (1.1.14 (a) (ii))

**Advice** Offside Rear Nail in tyre

**Advice** Nearside Front tyre worn from inner/outer shoulder.

**MOT #12** 2018-09-27 09:12

**MOT test number** 341153232794

**Result** 
✓ Passed

**Minor** Rear Inner Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt o/s/n/s (2.1.3 (g) (i))

**Advice** Head lamp washer not working.

Advice Front Brake disc worn, pitted or scored, but not seriously weakened upper lip. (1.1.14 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #11 2018-09-27 09:12

**MOT test number** 945806472845

**Result** X Failed

**Minor** Rear Inner Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt o/s/n/s (2.1.3 (g) (i))

**Pass with rectification** Nearside Position lamp not working (4.2.1 (a))

**Advice** Head lamp washer not working.

Advice Front Brake disc worn, pitted or scored, but not seriously weakened upper lip. (1.1.14 (a) (ii))

**MOT #10** 2017-10-03 08:52

**MOT test number** 282975017498

Result 

Passed

**Advice** Rear Brake pad(s) wearing thin inner pads (3.5.1g)

MOT #9 2016-09-27 09:18

MOT test number 224172072713

Result \rightarrow Passed

MOT #8 2015-10-02 09:16

MOT test number 888197214282

MOT #7 2014-10-03 11:35

**MOT test number** 348196274233

Result 

Passed

MOT #6 2013-09-03 10:53

**MOT test number** 315966943279

Result \rightarrow Passed

**Notice** Non obligatory mirror damaged

CarCheck.co.uk page 5/13



MOT #1

Result

**Advice** 

**MOT** test number

Tyre worn close to the legal limit (4.1.E.1)

## **BD06UGN**

report date: 2024-03-28

2009-06-26 10:30

603137379151

✓ Passed

MOT #5		2012-09-11 10:23
MOT test number		665685152262
Result		<b>✓</b> Passed
MOT #4		2011-08-25 10:28
MOT test number		798867431249
Result		<b>✓</b> Passed
MOT #3		2011-08-25 10:28
MOT test number		307037031237
Result		<b>≍</b> Failed
Pass with rectification Offs	ide Stop lamp not working (1.2.1b)	
MOT #2		2010-08-25 09:20
MOT test number		453337230242
Result		<b>✓</b> Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

#### Tax & MOT check





Tax status	Expired at 14 December 2021
Days left	867 days too late
MOT expiry date	26 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner	history
-------	---------

·	
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	
***************************************	
*********	
*************	
	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-06-20
Last registration	2023-07-27
Complete history	See info



Registration #1	2006-06-20	29 mi
Registration #2	2009-06-26	31.417 mi
Registration #3	2010-08-25	62.092 mi
Registration #4	2011-08-25	78.303 mi
Registration #5	2012-09-11	86.017 mi
Registration #6	2013-09-03	91.307 mi
Registration #7	2014-10-03	96.320 mi
Registration #8	2015-10-02	101.281 mi
Registration #9	2016-09-27	107.530 mi
Registration #10	2017-10-03	111.729 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		71.777 au

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

### Safety ratings

NCAP rating	***
Video	see crash video



## Dimensions & weight

Width	2060 mm
Height	1447 mm
Length	4905 mm
Wheel base	2909 mm
Kerb weight	1790 kg
Max. allowed weight	2275 kg

### Additional information

Fuel tank capacity	69 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	01265727G

CarCheck.co.uk page 13/13