




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF SE TSI
Colour	Silver
Year of manufacture	2008
Top speed	120 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	157 g/km
CO2 label	G





MOT history

MOT expiry date	2021-03-11
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	20
Total items failed	5

MOT #11 2020-03-12 15:37

MOT test number 222804916338

Result ✓ Passed

Next expiry date 2021-03-11

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))

MOT #10 2020-03-12 15:36

MOT test number 824288990255

Result ✗ Failed

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Offside Front Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #9**

2019-03-06 12:44

MOT test number

809138330184

Result

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #8

2019-02-11 15:30

MOT test number

725035638269

Result

✗ Failed

- Fail** Driver's view of the road through the swept area of the windscreen materially affected by an obstruction Air freshener (3.1 (a) (ii))
- Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Brake pedal has insufficient reserve travel (1.1.2 (a))
- Advice** Nearside Front Seat belt slightly damaged (7.1.2 (b) (i))
- Advice** Nearside Front Road wheel slightly distorted Alloy has a large chunk missing (5.2.2 (c) (i))
- Minor** Nearside Rear Tyre obviously under inflated Perished and cracking (5.2.3 (h) (i))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement Various (5.3.4 (a) (i))

MOT #7

2018-02-02 16:21

MOT test number

342605433776

Result

✓ Passed

- Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #6** 2017-01-06 12:49**MOT test number** 612229931799**Result** ✓ Passed**MOT #5** 2016-01-11 10:49**MOT test number** 319320506500**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**MOT #4** 2014-09-16 15:01**MOT test number** 719789854286**Result** ✓ Passed**MOT #3** 2013-09-30 12:06**MOT test number** 316793973459**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2012-10-26 12:21**MOT test number** 455690302314**Result** ✓ Passed**MOT #1** 2011-09-28 10:54**MOT test number** 646111971239**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

X

Untaxed

Tax expired:
6 January 2021

X

MOT

Expired:
11 March 2021

Tax status	Expired at 6 January 2021
Days left	1210 days too late
MOT expiry date	11 March 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	NA58EKU
Plate since	2019-03-29
Current registration	NA58EKU
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2008-09-25
Last registration	2020-03-12
Complete history	See info



Registration #1	2008-09-25	26 mi
Registration #2	2011-09-28	23.616 mi
Registration #3	2012-10-26	32.430 mi
Registration #4	2013-09-30	40.574 mi
Registration #5	2014-09-16	47.305 mi
Registration #6	2016-01-11	56.513 mi
Registration #7	2019-03-20	55.277 mi
Registration #8	2019-03-20	55.277 mi
Registration #9	2019-03-20	55.277 mi
Registration #10	2019-03-20	55.277 mi
Registration #11	2019-03-20	55.277 mi
Registration #12	2019-03-20	55.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1592 mm
Length	4204 mm
Wheel base	2578 mm
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

CAX038895