



UK

LM02ATO

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BORA
Colour	Black
Year of manufacture	-
Gearbox	-

Engine & fuel consumption

Fuel type	Petrol
-----------	--------



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-11-01
Pictures	18
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-31
Pictures	0
Listing price	View report

source: autotrader.co.uk

**MOT history**

MOT #22	2022-03-16 13:04
MOT test number	677940433562
Result	✓ Passed
Next expiry date	2023-03-26
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #21	2021-03-22 12:34
MOT test number	866352455343
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Nearside and Offside Mc Pherson strut have a slight movement at its upper attachment
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #20**

2021-03-20 14:12

MOT test number

831684337722

Result**✗ Failed**

- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Offside Front Headlamp lens seriously defective (4.1.1 (b) (ii))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Front Nearside and Offside Mc Pherson strut have a slight movement at its upper attachment
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Headlamp lens seriously defective (4.1.1 (b) (ii))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #19

2020-03-18 16:06

MOT test number

402717785768

Result**✓ Passed**

- Advice** Rear Nearside and Offside brake disc corroded
- Advice** Front Nearside and Offside brake disc corroded
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #18**

2020-03-11 18:01

MOT test number

432762900351

Result

✗ Failed

- Advice** Rear Nearside and Offside brake disc corroded
- Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Nearside and Offside brake disc corroded
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #17

2019-03-23 14:58

MOT test number

735650370624

Result

✓ Passed

- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Minor** Nearside Front Headlamp lens slightly defective beam image pattern only just visible (4.1.1 (b) (i))
- Advice** Service brake pedal has little reserve travel
- Advice** Front exhaust mount bracket broken
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Offside Front Headlamp lens slightly defective beam image pattern only just visible (4.1.1 (b) (i))
- Advice** Wet inside boot
- Advice** Fuel cap sealing washer cracking/splitting
- Advice** Engine covers fitted obscuring the view to some components

**MOT #16** 2018-03-06 14:59**MOT test number** 353154650967**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #15** 2017-03-03 16:54**MOT test number** 341537603606**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #14** 2016-03-12 14:47**MOT test number** 959277533262**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #13** 2016-03-12 13:53**MOT test number** 339778874264**Result** ✗ Failed**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #12** 2015-03-27 09:27**MOT test number** 886046885009**Result** ✓ Passed

**MOT #11** 2014-03-25 15:19**MOT test number** 418254284017**Result** ✓ Passed**MOT #10** 2014-03-24 15:37**MOT test number** 427263984078**Result** ✗ Failed

- Fail** Offside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Nearside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)
- Fail** Offside Rear Rear wheel bearing has excessive play (2.6.2)

MOT #9 2013-05-02 15:18**MOT test number** 286272223460**Result** ✓ Passed

- Notice** Nsf tyre wall cracked
- Advice** Rear registration plate faded but not likely to be misread (6.3.1d)

MOT #8 2013-05-01 11:17**MOT test number** 128751923192**Result** ✗ Failed

- Advice** Rear registration plate faded but not likely to be misread (6.3.1d)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Centre Front Exhaust system not adequately supported (7.1.1)
- Notice** Nsf tyre wall cracked
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #7** 2012-04-30 13:52**MOT test number** 578921522146**Result** ✓ Passed

- Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #6 2011-05-19 11:40**MOT test number** 396829431171**Result** ✓ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Notice** Oil leak
- Notice** Centre exhaust mounting broken but not considered insecure due to mounting housing bracket/undercover
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #5 2010-05-05 15:13**MOT test number** 262215820406**Result** ✓ Passed**MOT #4** 2009-05-21 11:00**MOT test number** 741861549139**Result** ✓ Passed



MOT #3	2008-05-16 13:52
MOT test number	691387438104
Result	✓ Passed
MOT #2	2007-05-24 11:01
MOT test number	464814547120
Result	✓ Passed
MOT #1	2006-05-16 12:01
MOT test number	171926036193
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2002-05-31
Last registration	2022-03-16
Complete history	See info



Registration #1	2002-05-31	22 mi
Registration #2	2006-05-16	65.685 mi
Registration #3	2007-05-24	77.214 mi
Registration #4	2008-05-16	87.503 mi
Registration #5	2009-05-21	96.724 mi
Registration #6	2010-05-05	100.429 mi
Registration #7	2011-05-19	103.007 mi
Registration #8	2012-04-30	104.904 mi
Registration #9	2013-05-01	106.332 mi
Registration #10	2013-05-02	106.368 mi
Registration #11	2014-03-24	108.139 mi
Registration #12	2014-03-25	108.139 mi
Registration #13	2015-03-27	108.505 mi
Registration #14	2015-05-20	108.505 mi
Registration #15	2015-05-20	108.505 mi
Registration #16	2015-05-20	108.505 mi
Registration #17	2015-05-20	108.505 mi
Registration #18	2015-05-20	108.505 mi
Registration #19	2015-05-20	108.505 mi
Registration #20	2015-05-20	108.505 mi
Registration #21	2015-05-20	108.505 mi
Registration #22	2015-05-20	108.505 mi
Registration #23	2015-05-20	108.505 mi
Registration #24	2015-05-20	108.505 mi
Registration #25	2015-05-20	108.505 mi



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Engine number NOT KNOWN