



PEUGEOT



report date: 2024-03-30

General information

Make	PEUGEOT
Model	307 SPORT HDI
Colour	Red
Year of manufacture	-
Top speed	129 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-07
Pictures	10
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #17	2022-06-28 08:58
MOT test number	564159955584
Result	✓ Passed
Next expiry date	2023-06-28

MOT #16	2021-06-29 12:36
MOT test number	220320160174
Result	✓ Passed
Advice	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Fuel additive support strap corroded

MOT #15	2021-06-17 10:03
MOT test number	472606830189
Result	✗ Failed
Advice	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Fuel additive support strap corroded
Fail	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14	2020-06-22 13:50
MOT test number	902470011727
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13** 2020-06-22 09:13**MOT test number** 848625022399**Result** ✗ Failed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure inner edge (5.2.3 (d) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12** 2019-05-02 10:38**MOT test number** 460125209548**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))**MOT #11** 2018-05-04 13:18**MOT test number** 276219594764**Result** ✓ Passed**MOT #10** 2017-05-09 12:58**MOT test number** 869152630921**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit on limit (4.1.E.1)**Advice** Offside Rear tyre inner wall splitting**Advice** Offside Rear Tyre worn close to the legal limit on limit (4.1.E.1)

**MOT #9** 2017-05-09 10:26**MOT test number** 441973510657**Result** ✗ Failed**Fail** Nearside Front Steering system has excessive free play detected at the steering wheel (steering rack fitted) (2.2.A.1b)**Advice** Offside Rear Tyre worn close to the legal limit on limit (4.1.E.1)**Advice** Offside Rear tyre inner wall splitting**Advice** Nearside Rear Tyre worn close to the legal limit on limit (4.1.E.1)**MOT #8** 2016-04-28 13:43**MOT test number** 287560468297**Result** ✓ Passed**MOT #7** 2016-04-28 09:35**MOT test number** 790989588249**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #6** 2015-05-12 13:44**MOT test number** 307812135178**Result** ✓ Passed**Notice** Front brake discs lipped**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside rear lamp cracked**Notice** Play in nearside steering rack arm

**MOT #5** 2015-05-12 09:36**MOT test number** 367372035101**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside rear lamp cracked**Notice** Play in nearside steering rack arm**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Front brake discs lipped**MOT #4** 2014-04-04 14:15**MOT test number** 156714894454**Result** ✓ Passed**MOT #3** 2013-03-27 14:52**MOT test number** 999626683044**Result** ✓ Passed**MOT #2** 2012-03-27 11:04**MOT test number** 937767682056**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)



MOT #1	2011-03-30 08:27
MOT test number	825229981046
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KR08UJS
Plate since	2019-09-29
Current registration	KR08UJS
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-05-06
Last registration	2022-06-28
Complete history	See info



Registration #1	2008-05-06	18 mi
Registration #2	2011-03-30	28.987 mi
Registration #3	2012-03-27	38.547 mi
Registration #4	2013-03-27	46.841 mi
Registration #5	2014-04-04	53.876 mi
Registration #6	2015-05-12	59.594 mi
Registration #7	2015-05-12	59.595 mi
Registration #8	2016-04-28	63.463 mi
Registration #9	2016-04-28	63.463 mi
Registration #10	2017-05-09	66.427 mi
Registration #11	2017-05-09	66.427 mi
Registration #12	2017-05-09	66.427 mi
Registration #13	2017-05-09	66.427 mi
Registration #14	2017-05-09	66.427 mi
Registration #15	2017-05-09	66.427 mi
Registration #16	2017-05-09	66.427 mi
Registration #17	2017-05-09	66.427 mi
Registration #18	2017-05-09	66.427 mi
Registration #19	2017-05-09	66.427 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2

Engine number

DYUK4096137