



TOYOTA



report date: 2024-03-29

General information

| | |
|---------------------|---------------------|
| Make | TOYOTA |
| Model | RAV-4 D-4D XT-R AWD |
| Colour | Grey |
| Year of manufacture | 2011 |
| Top speed | 118 mph |
| 0 - 60 mph | 10.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 150 BHP |
| Max. torque | 340 Nm at 2.800 rpm |
| Engine capacity | 2.231 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.7 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 159 g/km |
| CO2 label | G |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-21 |
| Pictures | 3 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-22 |
| MOT pass rate | 67 % |
| MOT passed | 10 |
| Failed MOT tests | 5 |
| Total advice items | 25 |
| Total items failed | 9 |

MOT #15 2023-07-18 07:23

MOT test number 869402923821

Result ✓ Passed

Next expiry date 2024-07-22

Advice All the rear subframe & suspension is corroded.

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #14 2023-07-18 07:23

MOT test number 719778252033

Result ✗ Failed

Advice All the rear subframe & suspension is corroded.

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #13 2022-07-14 11:52

MOT test number 368091761764

Result ✓ Passed

**MOT #12** 2022-07-14 08:29**MOT test number** 899751648362**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #11** 2021-07-23 09:22**MOT test number** 398028331380**Result** ✓ Passed**MOT #10** 2020-10-07 14:26**MOT test number** 699717749593**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2020-10-07 08:40**MOT test number** 656392956564**Result** ✗ Failed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2019-10-16 08:50**MOT test number** 108827960151**Result** ✓ Passed**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2018-11-13 11:22**MOT test number** 448518053404**Result** ✓ Passed**MOT #6** 2018-11-12 13:34**MOT test number** 260891242626**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Obligatory mirror missing (3.3 (a))**Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #5** 2017-09-21 10:52**MOT test number** 705466433903**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



| | |
|------------------------|--|
| MOT #4 | 2016-09-23 11:23 |
| MOT test number | 597024762154 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |

| | |
|------------------------|---|
| MOT #3 | 2016-09-21 13:07 |
| MOT test number | 320334961515 |
| Result | ✗ Failed |
| Advice | Nearside Front Brake pad(s) wearing thin (3.5.1g) |
| Fail | Nearside Rear Shock absorber has a serious fluid leak (2.7.3) |
| Fail | Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |
| Fail | Offside Front Lower Front suspension ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2) |

| | |
|------------------------|--|
| MOT #2 | 2015-12-01 11:54 |
| MOT test number | 982265865261 |
| Result | ✓ Passed |
| Advice | Coil spring corroded both rear slightly (2.4.C.1b) |
| Advice | Rear tyres cracking on sidewalls |

| | |
|------------------------|------------------|
| MOT #1 | 2014-11-26 11:53 |
| MOT test number | 119640534328 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
22 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 62 |
| MOT expiry date | 22 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2011-12-10 |
| Last registration | 2023-07-18 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2011-12-10 | 10 mi |
| Registration #2 | 2014-11-26 | 32.455 mi |
| Registration #3 | 2015-12-01 | 44.803 mi |
| Registration #4 | 2016-09-21 | 52.878 mi |
| Registration #5 | 2016-09-23 | 52.880 mi |
| Registration #6 | 2017-09-21 | 63.466 mi |
| Registration #7 | 2018-11-12 | 73.964 mi |
| Registration #8 | 2018-11-13 | 73.967 mi |
| Registration #9 | 2019-10-16 | 78.661 mi |
| Registration #10 | 2019-10-16 | 78.661 mi |
| Registration #11 | 2019-10-16 | 78.661 mi |
| Registration #12 | 2019-10-16 | 78.661 mi |
| Registration #13 | 2019-10-16 | 78.661 mi |
| Registration #14 | 2019-10-16 | 78.661 mi |
| Registration #15 | 2019-10-16 | 78.661 mi |
| Registration #16 | 2019-10-16 | 78.661 mi |
| Registration #17 | 2019-10-16 | 78.661 mi |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1815 mm |
| Height | 1685 mm |
| Length | 4365 mm |
| Wheel base | 2560 mm |
| Kerb weight | 1650 kg |
| Max. allowed weight | 2190 kg |

Additional information

| | |
|-----------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |

Engine number

2AD0355304