



TOYOTA



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | TOYOTA |
| Model | CELICA VVTi |
| Colour | Silver |
| Year of manufacture | 2003 |
| Top speed | 127 mph |
| 0 - 60 mph | 8.7 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 140 BHP |
| Max. torque | 172 Nm at 4.200 rpm |
| Engine capacity | 1.794 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 27.4 mpg |
| Consumption extra urban | 45.6 mpg |
| Consumption combined | 36.7 mpg |
| CO2 emission | 185 g/km |
| CO2 label | I |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-28 |
| Pictures | 18 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2022-11-03 |
| MOT pass rate | 77 % |
| MOT passed | 17 |
| Failed MOT tests | 5 |
| Total advice items | 41 |
| Total items failed | 10 |

| | |
|------------------|--|
| MOT #22 | 2021-11-04 15:17 |
| MOT test number | 316421331754 |
| Result | ✓ Passed |
| Next expiry date | 2022-11-03 |
| Advice | Coil spring corroded All 4 Coil Springs (5.3.1 (b) (i)) |
| Minor | Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt Both Sides Front (2.1.3 (g) (i)) |
| Advice | Rear Exhaust has a minor leak of exhaust gases Before Backbox (6.1.2 (a)) |



MOT #21 2020-10-26 14:58

MOT test number 701624651169

| Result | | ✓ Passed |
|--------|---|----------|
| Advice | Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i)) | |
| Advice | Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear Valve stem slightly damaged (5.2.3 (j)) | |
| Advice | Offside Rear Inner Integral body structure is corroded but structural rigidity is not significantly reduced sill area (6.1.1 (c) (i)) | |
| Advice | Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i)) | |
| Advice | Brake pedal long/possible air in system | |
| Advice | Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

**MOT #20**

2020-10-23 09:11

MOT test number

974989398842

Result**✗ Failed**

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inside wall (5.2.3 (d) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Brake pedal long/possible air in system

Fail Nearside Rear Inner Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill area (6.1.1 (c) (i))

Fail Offside Front Coil spring mounting corroded and seriously weakened (5.3.1 (b) (i))

Advice Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Inner Integral body structure is corroded but structural rigidity is not significantly reduced sill area (6.1.1 (c) (i))

Advice Nearside Rear Valve stem slightly damaged (5.2.3 (j))

Fail Offside Front Macpherson strut corroded and seriously weakened (5.3.3 (b) (i))

Advice Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #19

2019-10-28 12:14

MOT test number

766616328511

Result**✓ Passed**

**MOT #18** 2018-10-24 14:22**MOT test number** 568800583702**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #17** 2018-10-24 09:22**MOT test number** 838309757817**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2017-10-20 09:07**MOT test number** 573375527189**Result** ✓ Passed**MOT #15** 2016-10-26 10:25**MOT test number** 417137713330**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #14** 2015-10-15 15:19**MOT test number** 174499812441**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #13** 2015-10-15 08:41**MOT test number** 731921306408**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #12** 2014-10-31 15:55**MOT test number** 228674804335**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2014-10-27 12:00**MOT test number** 525210704365**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside front brake binding (3.7.B.1)**Notice** Both rear tyres wearing inner Rear wiper rubber adrift**MOT #10** 2014-01-08 12:04**MOT test number** 316978904070**Result** ✓ Passed**MOT #9** 2013-01-03 10:30**MOT test number** 429253103047**Result** ✓ Passed

**MOT #8** 2011-12-23 13:50**MOT test number** 916067751303**Result** ✓ Passed**MOT #7** 2010-10-01 07:43**MOT test number** 141254070295**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2010-10-01 07:43**MOT test number** 874144270274**Result** ✗ Failed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2009-10-02 08:18**MOT test number** 350455379461**Result** ✓ Passed**MOT #4** 2008-08-13 15:55**MOT test number** 132726428234**Result** ✓ Passed**MOT #3** 2008-03-28 09:31**MOT test number** 574068988085**Result** ✓ Passed**Notice** Nail in offside front tyre



| | |
|-----------------|------------------|
| MOT #2 | 2007-06-20 11:53 |
| MOT test number | 221141277414 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2006-06-14 11:44 |
| MOT test number | 674865766177 |
| Result | ✓ Passed |

Notice All four tyres have some fine cracking in tread refer back to manufacture



Tax & MOT check

✕
Untaxed

Tax expired:
15 August 2022

✕
MOT

Expired:
3 November 2022

| | |
|------------------|---------------------------------|
| Tax status | Expired at 15 August 2022 |
| Days left | 623 days too late |
| MOT expiry date | 3 November 2022 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-03-29 |
| Current registration | ***** |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 23 |
| First mileage registration | 2003-06-19 |
| Last registration | 2021-11-04 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2003-06-19 | 9 mi |
| Registration #2 | 2006-06-14 | 14.548 mi |
| Registration #3 | 2007-06-20 | 19.753 mi |
| Registration #4 | 2008-03-28 | 22.983 mi |
| Registration #5 | 2008-08-13 | 24.189 mi |
| Registration #6 | 2009-10-02 | 34.387 mi |
| Registration #7 | 2010-10-01 | 39.864 mi |
| Registration #8 | 2011-12-23 | 44.941 mi |
| Registration #9 | 2013-01-03 | 49.246 mi |
| Registration #10 | 2014-01-08 | 53.400 mi |
| Registration #11 | 2014-10-27 | 53.544 mi |
| Registration #12 | 2014-10-31 | 53.544 mi |
| Registration #13 | 2015-01-01 | 53.544 mi |
| Registration #14 | 2015-01-01 | 53.544 mi |
| Registration #15 | 2015-01-01 | 53.544 mi |
| Registration #16 | 2015-01-01 | 53.544 mi |
| Registration #17 | 2015-01-01 | 53.544 mi |
| Registration #18 | 2015-01-01 | 53.544 mi |
| Registration #19 | 2015-01-01 | 53.544 mi |
| Registration #20 | 2015-01-01 | 53.544 mi |
| Registration #21 | 2015-01-01 | 53.544 mi |
| Registration #22 | 2015-01-01 | 53.544 mi |
| Registration #23 | 2015-01-01 | 53.544 mi |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|-------------|---------|
| Width | 1735 mm |
| Height | 1315 mm |
| Length | 4350 mm |
| Wheel base | 2600 mm |
| Kerb weight | 1145 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Engine number | 1ZZ1324678 |