



report date: 2024-03-29

General information

Make	FORD
Model	FUSION FUSION +
Colour	Silver
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 2


Date	2022-12-22
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-16
Pictures	34
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-10
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	16
Total items failed	3

MOT #16 2023-11-11 15:17

MOT test number 120320380274

Result ✓ Passed

Next expiry date 2024-11-10

- Advice** Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside side mirror housing loose
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #15 2023-01-12 09:11

MOT test number 930075367781

Result ✓ Passed



MOT #14	2022-09-13 15:49
----------------	------------------

MOT test number	216551219680
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #13	2021-09-16 11:17
----------------	------------------

MOT test number	924245252795
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #12	2021-09-16 11:17
----------------	------------------

MOT test number	909158828886
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
--------------------------------	--

MOT #11	2021-01-12 13:18
----------------	------------------

MOT test number	451208273147
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #10	2021-01-12 13:18
----------------	------------------

MOT test number	812959474623
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Front Brake disc in such a condition that it is seriously weakened x2 (1.1.14 (a) (ii))
--------------------------------	---

MOT #9	2019-07-22 12:46
---------------	------------------

MOT test number	322015837870
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2018-06-02 10:25
---------------	------------------

MOT test number	116449642241
------------------------	--------------

Result	✓ Passed
---------------	----------

**MOT #7** 2017-06-09 08:53**MOT test number** 110714700070**Result** ✓ Passed**MOT #6** 2016-08-02 10:52**MOT test number** 936868820899**Result** ✓ Passed**MOT #5** 2016-08-02 10:52**MOT test number** 913399086398**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2015-07-29 08:55**MOT test number** 805100715238**Result** ✓ Passed**Notice** Nearside rear tyre cracking**Advice** Nearside Rear wheel bearing has slight play (2.6.2)**Notice** Nearside front tyre sidewall damage**Notice** Items removed from driver's view prior to test**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-07-31 09:05**MOT test number** 758322814237**Result** ✓ Passed**MOT #2** 2013-07-31 11:02**MOT test number** 187712213277**Result** ✓ Passed



MOT #1	2012-07-16 09:59
MOT test number	388978492125
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
10 November 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	10 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2019-09-29
Current registration	XXXXX
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-08-10
Last registration	2023-11-11
Complete history	See info



Registration #1	2009-08-10	11 mi
Registration #2	2012-07-16	6.140 mi
Registration #3	2013-07-31	7.810 mi
Registration #4	2014-07-31	10.963 mi
Registration #5	2015-07-29	13.303 mi
Registration #6	2016-08-02	15.365 mi
Registration #7	2016-08-02	15.365 mi
Registration #8	2017-06-09	16.800 mi
Registration #9	2018-06-02	19.519 mi
Registration #10	2019-07-22	21.309 mi
Registration #11	2020-06-02	23.100 mi
Registration #12	2021-06-02	24.900 mi
Registration #13	2022-06-02	26.700 mi
Registration #14	2023-06-02	28.500 mi
Registration #15	2024-06-02	30.300 mi
Registration #16	2025-06-02	32.100 mi
Registration #17	2026-06-02	33.900 mi
Registration #18	2027-06-02	35.700 mi
Registration #19	2028-06-02	37.500 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9P21532