



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Red
Year of manufacture	2005
Top speed	102 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	117 Nm at 3.200 rpm
Engine capacity	1.341 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-30
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2025-01-09
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	21
Total items failed	10

MOT #21 2024-01-10 13:53**MOT test number** 691421411027**Result** ✓ Passed**Next expiry date** 2025-01-09**Advice** Offside Front Play in steering rack inner joint(s)**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #20** 2022-07-01 08:52**MOT test number** 175515725851**Result** ✓ Passed**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing slightly perished (5.2.3 (d) (ii))**MOT #19** 2022-07-01 08:52**MOT test number** 914262907639**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working 501 bulb (4.2.1 (a) (ii))**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing slightly perished (5.2.3 (d) (ii))

**MOT #18** 2021-07-02 09:00**MOT test number** 510575984457**Result** ✓ Passed**MOT #17** 2021-07-01 11:56**MOT test number** 737958883105**Result** ✗ Failed**Fail** Front Exhaust emissions likely to be affected by an exhaust leak flexi (8.2.2.1 (b))**Fail** Emissions not tested exhaust leak (8.2.1.2 (d))**MOT #16** 2020-07-13 08:27**MOT test number** 127325934060**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #15** 2019-07-29 15:05**MOT test number** 848013072779**Result** ✓ Passed**Advice** Offside Rear Tyre perishing and cracked**MOT #14** 2019-07-29 08:46**MOT test number** 778709491323**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Tyre perishing and cracked**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**Advice** Engine oil level on minimum

**MOT #13** 2018-08-01 15:32**MOT test number** 508040432176**Result** ✓ Passed**MOT #12** 2018-08-01 08:35**MOT test number** 241573580973**Result** ✗ Failed**Fail** Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a))**MOT #11** 2017-07-25 10:50**MOT test number** 177360454186**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2016-08-06 10:31**MOT test number** 800609745340**Result** ✓ Passed**Advice** Battery secured in place by wire**Advice** Rear Seat belts not inspected as seats are folded down and lots of items on top**MOT #9** 2015-07-29 10:11**MOT test number** 688980715244**Result** ✓ Passed**Notice** Battery secured in using wire**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2014-09-11 11:50**MOT test number** 297634354278**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2013-10-01 13:35**MOT test number** 865654973243**Result** ✓ Passed**Notice** Battery held in by wire**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2013-10-01 13:35**MOT test number** 429064573295**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Battery held in by wire**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-09-20 10:01**MOT test number** 888854162233**Result** ✓ Passed**MOT #4** 2011-09-13 15:18**MOT test number** 359986651213**Result** ✓ Passed**MOT #3** 2010-09-15 11:40**MOT test number** 980588450256**Result** ✓ Passed



MOT #2	2009-10-05 10:05
MOT test number	783778679242
Result	✓ Passed

MOT #1	2008-10-06 12:41
MOT test number	581950488257
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
9 January 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	9 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	WF55VJY
Plate since	2019-03-29
Current registration	WF55VJY
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-09-29
Last registration	2024-01-10
Complete history	See info



Registration #1	2005-09-29	16 mi
Registration #2	2008-10-06	7.324 mi
Registration #3	2009-10-05	9.762 mi
Registration #4	2010-09-15	10.888 mi
Registration #5	2011-09-13	13.560 mi
Registration #6	2012-09-20	15.977 mi
Registration #7	2013-10-01	17.629 mi
Registration #8	2014-09-11	18.930 mi
Registration #9	2015-07-29	19.674 mi
Registration #10	2016-08-06	21.367 mi
Registration #11	2017-07-25	26.938 mi
Registration #12	2018-06-20	28.277 mi
Registration #13	2019-06-20	29.277 mi
Registration #14	2020-06-20	30.277 mi
Registration #15	2021-06-20	31.277 mi
Registration #16	2022-06-20	32.277 mi
Registration #17	2023-06-20	33.277 mi
Registration #18	2024-01-10	34.277 mi
Registration #19	2024-01-10	35.277 mi
Registration #20	2024-01-10	36.277 mi
Registration #21	2024-01-10	37.277 mi
Registration #22	2024-01-10	38.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1076 kg
Max. allowed weight	1500 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	G4EA5769430