





report date: 2024-03-29

### General information

Make	MINI
Model	MINI ONE D
Colour	Black
Year of manufacture	2013
Top speed	114 mph
0 - 60 mph	11.4 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



# Internet history

### Entry 1

Date 2021-06-03

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



# MOT history

MOT expiry date	2025-02-27
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	25
Total items failed	2

MOT #10		2024-02-27 08:29
MOT test i	number	305629587317
Result		✓ Passed
Next expi	ry date	2025-02-27
Advice	Nearside Suspension arm pin or bush worn but not resulting in excessive m	ovement (5.3.4 (a) (i))
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))		
Advice	Offside Suspension arm pin or bush worn but not resulting in excessive mov	vement (5.3.4 (a) (i))

MOT #9	2023-02-28 15:28
MOT test number	597412570361
Result	✓ Passed
Minor Offside Rear Stop lamp(s) with a multiple light source up to 1/2 not function	ning (4.3.1 (a) (i))
Advice Offside Front Nail in tyre	
Minor Nearside Rear Stop lamp(s) with a multiple light source up to 1/2 not function	oning (4.3.1 (a) (i))
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/12



**Advice** 

HJ13ZNZ report date: 2024-03-29

MOT test number

S49186017890

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7

MOT test number

418581472952

Result

Minor

Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT test number

330868294616

Result

Fail Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

 MOT #5
 2020-02-08 11:44

 MOT test number
 587292216925

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



 MOT #4
 2019-02-16 10:46

 MOT test number
 227792148938

 Result
 ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Engine covers fitted

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Undertrays fitted.

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2017-06-02 09:44 **MOT** test number 213602678203 Result × Failed Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) Advice Engine covers fitted Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) **Advice** Undertrays fitted. **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #1
 2016-06-07 15:13

 MOT test number
 707743626749

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



### Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	27 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	biotom,
UWNEI	nisioiv

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NA SIL
Plate since	
Current registration	NK SILE
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-06-28
Last registration	2024-02-27
Complete history	See info



Registration #1	2013-06-28	25 mi
Registration #2	2016-06-07	25.380 mi
Registration #3	2017-06-02	36.798 mi
Registration #4	2017-06-02	36.798 mi
Registration #5	2019-02-16	40.536 mi
Registration #6	2020-02-08	43.955 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

# Additional information

Fuel tank capacity	40 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/1

Number of axles 2

**Engine number** 70728575