





report date: 2024-03-28

General information

Make	AUDI
Model	A4 TDI SPORT DPF
Colour	Black
Year of manufacture	2006
Top speed	131 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.986 сс
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	52.3 mpg
Consumption combined	43.5 mpg
CO2 emission	175 g/km
CO2 label	Н



CarCheck.co.uk page 1/17



report date: 2024-03-28

Internet history

Entry 2

Date 2022-12-29

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-01-27
Pictures	10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/17



report date: 2024-03-28

MOT history

MOT expiry date	2024-01-15
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	83
Total items failed	7

MOT #24	2023-01-16 16:59
MOT test number	690801947921
Result	✓ Passed
Next expiry date	2024-01-15
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #23	2023-01-13 13:07
MOT test number	779931027876
Result	× Failed
DANGEROUS Offside Rear Tyre has a tear, caused by separation or partial failure of it (d) (ii))	s structure (5.2.3
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))	
MAJOR Oil leaking excessively from engine (8.4.1 (a) (i))	
DANGEROUS Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #22		2022-04-12 12:32
MOT test n	number	637960796872
Result		✓ Passed
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge Perished (5.2.3 (e)))

CarCheck.co.uk page 3/17



report date: 2024-03-28

MOT test number

Result

Advice Engine covers &Under shield fitted obscuring some components

Rear Brake hose slightly deteriorated Both sides (1.1.12 (b) (ii))

MOT #20

MOT test number

193350517853

Result

Advice Engine covers & Under shield fitted obscuring some components

Advice Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #19 2020-10-10 12:12 657864706991 **MOT** test number Result Failed **Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii)) **DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) Advice Advice Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii)) Advice Engine covers & Under shield fitted obscuring some components **DANGEROUS** Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) **Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

CarCheck.co.uk page 4/17



report date: 2024-03-28

MOT #18 2020-09-22 11:27

MOT test number 912839451165

Result X Failed

MAJOR Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Engine cover and undertrays fitted obscuring view of testable items

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Front tyre badly worn on inner edge close to cord construction, low on tread

MAJOR Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt front arm, cover perished and split (5.3.4 (b) (ii))

Advice Offside Rear Brake hose slightly deteriorated perishing and cracking up (1.1.12 (b) (ii))

Advice Various damage around vehicle

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Exhaust corroding

(b) (i))

(i))

MAJOR Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt front arm, cover perished and split (5.3.4 (b) (ii))

Minor Horn not working properly (7.7 (a) (i))

Advice Nearside Rear Brake hose slightly deteriorated perishing and cracking up (1.1.12 (b) (ii))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Wheel centre caps fitted - retainers not checked

MOT #17 2019-07-19 12:24

MOT test number 643821058913

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated front arm (5.3.4 (b)

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Power steering close to minimum mark (2.1.5 (b) (i))

CarCheck.co.uk page 5/17



report date: 2024-03-28

MOT #16 2018-07-13 14:26

MOT test number 647580297853

MOT #15 2017-06-06 09:00

MOT test number 852384399391

Advice Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Advice Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Front Lower Suspension arm has slight play in a ball joint Rear arms (2.4.G.2)

Advice Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #14 2017-06-06 09:00

MOT test number 440585908931

Result × Failed

Advice Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Advice Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Pass with rectification Nearside Rear Rear position lamp(s) not working (1.1.A.3b)

Advice Offside Front Lower Suspension arm has slight play in a ball joint Rear arms (2.4.G.2)

Advice Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #13 2016-06-17 16:17

MOT test number 523088295271

Advice Rear brake discs are badly corroded & pitted

Advice N/s front tyre nailed

Advice Under-tray & engine cover hinders view to some testable items

CarCheck.co.uk page 6/17



report date: 2024-03-28

MOT #12

MOT test number

289152365160

Result

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT test number

629392365111

Result

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components


Pass with rectification Offside Rear position lamp(s) not working (1.1.A.3b)

MOT #10		2014-05-21 08:05
MOT test	number	868341344184
Result		✓ Passed
Notice	Both number plateshave thin white lines in the charcaters	
Notice	Under-trays fitted obscuring some underside components	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	Front bumper trims dangling down	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Engine covers fitted obscuring some components in the engine bay	

CarCheck.co.uk page 7/17



report date: 2024-03-28



MOT #8		2013-05-22 16:01
MOT test	number	365252243127
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3	3.1d)
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	Under-trays fitted obscuring some underside components	
Notice	High level rear brake light inoperative, warning light on dash.	

CarCheck.co.uk page 8/17



report date: 2024-03-28

MOT test number

Result

Notice Under-trays fitted obscuring some underside components

Notice High level brake light not working

Notice Engine covers fitted obscuring some components in the engine bay

MOT test number

Result

Notice Front brake discs worn/pitted

Notice Nail in nearside rear tyre

Notice Rear brake discs slightly worn

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #5 2011-06-14 09:54 **MOT** test number 568935361150 Result × Failed **Advice** Front Brake pad(s) wearing thin (3.5.1g) Notice Nail in nearside rear tyre Fail An item not tested (Manual) Notice Rear brake discs slightly worn Notice Front brake discs worn/pitted

 MOT #4
 2010-06-29 11:05

 MOT test number
 164040280177

 Result
 ✓ Passed

CarCheck.co.uk page 9/17



report date: 2024-03-28

MOT #3 2009-06-16 09:29

MOT test number 231437869182

MOT #2 2009-06-15 10:07

MOT test number 691936369174

Result X Failed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #1 2009-04-03 11:17

MOT test number 634493399097

Result \rightarrow Passed

Notice Offside front disc rusty on braking surface

CarCheck.co.uk page 10/17



report date: 2024-03-28

Tax & MOT check



Expired: 15 January 2024 X MOT

Tax status	Expired at 20 October 2023
Days left	192 days too late
MOT expiry date	15 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 11/17



report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/17



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 13/17



funda scincos

YP06NBB

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this AUDI had different number plates. obser of plates

CarCheck.co.uk page 14/17



report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 15/17



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2006-05-19
Last registration	2023-01-16
Complete history	See info



Registration #1	2006-05-19	19 mi
Registration #2	2009-04-03	41.801 mi
Registration #3	2009-06-15	42.575 mi
Registration #4	2009-06-16	42.575 mi
Registration #5	2010-06-29	48.483 mi
Registration #6	2011-06-14	53.342 mi
Registration #7	2011-06-14	53.342 mi
Registration #8	2012-05-30	58.269 mi
Registration #9	2013-05-22	62.414 mi
Registration #10	2014-05-20	67.389 mi
Registration #11	2014-05-21	67.389 mi
Registration #12	2015-06-11	71.430 mi
Registration #13	2016-06-17	73.716 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 esi
Registration #24		71.777 es
Registration #25		11.777 es
Registration #26		11.777 es

CarCheck.co.uk page 16/17



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1391 mm
Length	4573 mm
Wheel base	2650 mm
Kerb weight	1600 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 17/1

Number of axles 2

Engine number BPW 020814