



report date: 2024-03-29

General information

Make	MINI
Model	COOPER S
Colour	Grey
Year of manufacture	2017
Top speed	144 mph
0 - 60 mph	6.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	189 BHP
Max. torque	280 Nm at 1.250 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2


Date	2021-02-02
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 1

Date	2021-01-28
Pictures	26
Listing price	View report



source: [yesauto.com](https://www.yesauto.com)

**MOT history**

MOT expiry date	2025-02-04
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #8 2024-02-05 09:22**MOT test number** 897481044605**Result** Passed**Next expiry date** 2025-02-04

- Advice** Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake pad light is on, pads no worn down to wire. sensor fault
- Advice** Offside Rear Tyre slightly damaged (5.2.3 (d) (ii))

MOT #7 2023-02-01 09:07**MOT test number** 664498154531**Result** Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2022-01-20 16:10**MOT test number** 434963973543**Result** Passed

**MOT #5** 2022-01-20 10:51**MOT test number** 833323819576**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #4** 2021-01-18 11:50**MOT test number** 909544406124**Result** ✓ Passed**MOT #3** 2020-07-01 14:50**MOT test number** 497109787798**Result** ✓ Passed**MOT #2** 2020-07-01 12:01**MOT test number** 275462577348**Result** ✗ Failed**Advice** Offside Front Outer Tyre slightly damaged Outer side wall (5.2.3 (d) (ii))**Fail** Nearside Front Tyre has ply or cords exposed Ply exposed in 2 cuts (5.2.3 (d) (ii))**MOT #1** 2020-06-22 05:42**MOT test number** 928489578679**Result** ✓ Passed**Advice** COVID-19 6 MONTH EXTENSION



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
4 February 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	4 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-06-30
Last registration	2024-02-05
Complete history	See info



Registration #1	2017-06-30	22 mi
Registration #2	2020-07-01	27.195 mi
Registration #3	2020-07-01	27.195 mi
Registration #4	2021-01-18	31.465 mi
Registration #5	2022-05-20	35.277 mi
Registration #6	2022-05-20	35.277 mi
Registration #7	2022-05-20	35.277 mi
Registration #8	2022-05-20	35.277 mi
Registration #9	2022-05-20	35.277 mi
Registration #10	2024-02-05	35.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1727 mm
Height	1425 mm
Length	3982 mm
Wheel base	2567 mm
Kerb weight	1295 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	44 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	F491H382