



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 AIRPLAY PLUS
Colour	Blue
Year of manufacture	2007
Top speed	98 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	94 Nm at 3.300 rpm
Engine capacity	1.124 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-02-09
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-10
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	43
Total items failed	2

MOT #17	2024-03-11 12:21
MOT test number	816185140994
Result	✓ Passed
Next expiry date	2025-03-10
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge low inner edge (5.2.3 (e))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Oil leak
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Exhaust system corroded
Advice	Offside Rear Tyre worn close to legal limit/worn on edge advice to change (5.2.3 (e))

**MOT #16**

2023-03-01 09:08

**MOT test number**

680635945145

**Result**

✓ Passed

- Advice** Exhausts system corroded
- Advice** Offside Front Tyre worn close to legal limit/worn on edge close to limit (5.2.3 (e))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #15**

2022-02-11 14:17

**MOT test number**

458133787266

**Result**

✓ Passed

- Advice** Nearside Front Seatbelt fitted with red tape
- Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))
- Advice** Front Brake pad(s) wearing thin Both (1.1.13 (a) (ii))
- Advice** Underbody slightly rusty
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2021-03-08 10:28**MOT test number** 815555729036**Result** ✓ Passed

- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #13** 2020-03-23 11:29**MOT test number** 998927010988**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2019-03-19 11:14**MOT test number** 989060367114**Result** ✓ Passed

- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #11** 2018-03-15 11:25**MOT test number** 403989029174**Result** ✓ Passed

- Advice** Rear EXHAUST MOUNT BRACKET BROKEN

**MOT #10** 2017-03-21 15:11**MOT test number** 511875054198**Result** ✓ Passed

- Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #9** 2016-03-10 10:59**MOT test number** 345955296002**Result** ✓ Passed**MOT #8** 2015-01-28 11:42**MOT test number** 885248225004**Result** ✓ Passed**Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #7** 2014-02-13 14:20**MOT test number** 899644844044**Result** ✓ Passed**Notice** Both fron tyres worn outer edges**Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #6** 2013-02-25 16:51**MOT test number** 279516953038**Result** ✓ Passed**MOT #5** 2012-01-14 14:34**MOT test number** 146334112098**Result** ✓ Passed**MOT #4** 2012-01-14 14:34**MOT test number** 779474112004**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #3** 2011-01-15 12:18**MOT test number** 369085111066**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2011-01-15 11:59**MOT test number** 997025811040**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2010-01-08 10:28**MOT test number** 712508500028**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front wipers split



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
10 March 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	10 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-05-18
Last registration	2024-03-11
Complete history	<a href="#">See info</a>



Registration #1	2007-05-18	28 mi
Registration #2	2010-01-08	18.881 mi
Registration #3	2011-01-15	25.605 mi
Registration #4	2011-01-15	25.605 mi
Registration #5	2012-01-14	32.070 mi
Registration #6	2013-02-25	38.082 mi
Registration #7	2014-02-13	45.219 mi
Registration #8	2015-01-28	52.216 mi
Registration #9	2016-03-10	55.268 mi
Registration #10	2016-03-10	55.268 mi
Registration #11	2016-03-10	55.268 mi
Registration #12	2016-03-10	55.268 mi
Registration #13	2016-03-10	55.268 mi
Registration #14	2016-03-10	55.268 mi
Registration #15	2016-03-10	55.268 mi
Registration #16	2016-03-10	55.268 mi
Registration #17	2016-03-10	55.268 mi
Registration #18	2016-03-10	55.268 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1659 mm
Height	1477 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	932 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FP7W4926126