



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK200K AVANTGARDE
Colour	Silver
Year of manufacture	2009
Top speed	144 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg
CO2 emission	214 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-02
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2025-03-24
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	28
Total items failed	6

MOT #17	2024-03-25 15:55
MOT test number	302489210924
Result	✓ Passed
Next expiry date	2025-03-24

MOT #16	2024-03-14 13:22
MOT test number	549005851670
Result	✗ Failed
<b>DANGEROUS</b> Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
<b>Pass with rectification</b>	Nearside Front Position lamp not working (4.2.1 (a) (ii))
<b>Pass with rectification</b>	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Pass with rectification</b>	Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #15	2022-10-28 11:48
MOT test number	638037238880
Result	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2022-10-28 11:48**MOT test number** 659387311421**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2021-10-21 10:46**MOT test number** 439037623065**Result** ✓ Passed**MOT #12** 2021-10-20 10:21**MOT test number** 196735833843**Result** ✗ Failed**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11** 2020-10-23 09:33**MOT test number** 173786422084**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge both side rear (5.2.3 (e))**MOT #10** 2019-10-22 08:04**MOT test number** 512539367485**Result** ✓ Passed**Advice** Exhaust pipe cracking**Advice** Brake pipe corroded, covered in grease or other material both side front to rear (1.1.11 (c))

**MOT #9** 2019-10-21 10:22**MOT test number** 537651717086**Result** ✗ Failed**MAJOR** Position lamp not working both side front (4.2.1 (a) (ii))**Advice** Brake pipe corroded, covered in grease or other material both side front to rear (1.1.11 (c))**DANGEROUS** Tyre has ply or cords exposed both side front (5.2.3 (d) (ii))**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Exhaust pipe cracking**MOT #8** 2018-10-23 10:06**MOT test number** 651708180673**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge both side front (5.2.3 (e))**Advice** Brake pipe corroded, covered in grease or other material both side front to rear (1.1.11 (c))**MOT #7** 2017-06-27 09:28**MOT test number** 231339864296**Result** ✓ Passed**Advice** Surface corrosion on discs, appears to have been stood.**Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Engine/under/sill covers**MOT #6** 2016-02-20 14:16**MOT test number** 671224153298**Result** ✓ Passed**Advice** Centre exhaust mounting broken but system still secure**Advice** Rear both rear tyres worn on inner edges

**MOT #5** 2016-02-20 11:00**MOT test number** 153880158685**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Centre exhaust mounting broken but system still secure**Advice** Rear both rear tyres worn on inner edges**MOT #4** 2014-12-04 13:30**MOT test number** 918718834375**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-09-16 15:50**MOT test number** 778279053204**Result** ✓ Passed**MOT #2** 2013-04-19 10:05**MOT test number** 346229103118**Result** ✓ Passed**MOT #1** 2012-03-30 10:40**MOT test number** 168000292488**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
24 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	24 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	<b>BJ09HUZ</b>
Plate since	2019-06-29
Current registration	<b>BJ09HUZ</b>
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-04-30
Last registration	2024-03-25
Complete history	<a href="#">See info</a>



Registration #1	2009-04-30	14 mi
Registration #2	2012-03-30	32.492 mi
Registration #3	2013-04-19	45.220 mi
Registration #4	2013-09-16	51.046 mi
Registration #5	2014-12-04	65.192 mi
Registration #6	2016-02-20	101.249 mi
Registration #7	2016-02-20	101.249 mi
Registration #8	2017-06-27	103.079 mi
Registration #9	2018-10-23	109.093 mi
Registration #10	2019-10-21	114.291 mi
Registration #11	2020-03-20	115.277 mi
Registration #12	2020-03-20	115.277 mi
Registration #13	2020-03-20	115.277 mi
Registration #14	2020-03-20	115.277 mi
Registration #15	2020-03-20	115.277 mi
Registration #16	2020-03-20	115.277 mi
Registration #17	2020-03-20	115.277 mi
Registration #18	2020-03-20	115.277 mi
Registration #19	2020-03-20	115.277 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1685 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195531120793