



MM08VXC

report date: 2024-03-28

General information

Make	CITROEN
Model	C5 VTR PLUS HDI
Colour	Silver
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg





MOT history

MOT #18	2023-03-08 11:26
MOT test number	213110048907
Result	✓ Passed
Next expiry date	2024-03-07
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

MOT #17	2023-03-08 11:26
MOT test number	702292626536
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #16	2022-01-27 13:12
MOT test number	167576975463
Result	✓ Passed

**MOT #15**

2022-01-27 13:12

MOT test number

800724118696

Result**✗ Failed****Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #14**

2021-02-24 15:39

MOT test number

933086920451

Result**✓ Passed****Advice** Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #13**

2021-02-24 15:39

MOT test number

557901048869

Result**✗ Failed****Advice** Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Front Windscreen wiper missing (3.4 (a))**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Front Headlamp aim too low and too far to the right. (4.1.2 (a))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #12** 2020-01-10 10:25**MOT test number** 244423968217**Result** ✓ Passed**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2020-01-10 09:41**MOT test number** 177502846136**Result** ✗ Failed**Fail** Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #10** 2019-01-31 12:29**MOT test number** 959413939417**Result** ✓ Passed**MOT #9** 2018-03-17 11:50**MOT test number** 115996288784**Result** ✓ Passed**MOT #8** 2018-03-16 15:40**MOT test number** 411864338882**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)

**MOT #7** 2017-03-16 15:45**MOT test number** 937751421498**Result** ✓ Passed**Advice** Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-03-24 14:41**MOT test number** 473975179604**Result** ✓ Passed**Advice** Centre stop lamp inoperative.**MOT #5** 2015-03-19 15:52**MOT test number** 836548275022**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #4** 2014-03-18 15:30**MOT test number** 567887074073**Result** ✓ Passed**MOT #3** 2013-04-15 16:58**MOT test number** 386705503155**Result** ✓ Passed**MOT #2** 2012-07-10 11:40**MOT test number** 237962192494**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #1	2011-07-15 12:13
MOT test number	858006391156
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,200
Auction value	£ 19,200
Average private trade value	£ 19,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-07-28
Last registration	2023-03-08
Complete history	See info



Registration #1	2008-07-28	13 mi
Registration #2	2011-07-15	28.179 mi
Registration #3	2012-07-10	35.683 mi
Registration #4	2013-04-15	41.783 mi
Registration #5	2014-03-18	49.875 mi
Registration #6	2015-03-19	58.555 mi
Registration #7	2016-03-24	66.741 mi
Registration #8	2017-03-16	75.100 mi
Registration #9	2018-03-16	83.664 mi
Registration #10	2018-03-17	83.664 mi
Registration #11	2019-03-20	92.227 mi
Registration #12	2019-03-20	92.227 mi
Registration #13	2019-03-20	92.227 mi
Registration #14	2019-03-20	92.227 mi
Registration #15	2019-03-20	92.227 mi
Registration #16	2019-03-20	92.227 mi
Registration #17	2019-03-20	92.227 mi
Registration #18	2019-03-20	92.227 mi
Registration #19	2019-03-20	92.227 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1853 mm
Height	1471 mm
Length	4829 mm
Wheel base	2750 mm
Kerb weight	1655 kg
Max. allowed weight	2276 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYVP4052087