



report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE CLASSIC
Colour	Grey
Year of manufacture	2004
Top speed	125 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	325 Nm at 1.800 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.9 mpg
Consumption extra urban	62.1 mpg
Consumption combined	50.3 mpg
CO2 emission	149 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-07-09
Pictures	2
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-02-08
-----------------	------------

MOT pass rate	71 %
---------------	------

MOT passed	15
------------	----

Failed MOT tests	6
------------------	---

Total advice items	30
--------------------	----

Total items failed	10
--------------------	----

MOT #21	2021-02-09 16:58
---------	------------------

MOT test number	135885660660
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2022-02-08
------------------	------------

Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
--------	---

Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
--------	---

MOT #20	2021-02-08 10:09
---------	------------------

MOT test number	833988120369
-----------------	--------------

Result	✗ Failed
--------	----------

MAJOR	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
-------	--

Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
--------	---

MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
-------	---

Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
--------	---

**MOT #19**

2020-02-07 10:53

MOT test number

268260956369

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Lower Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #18**

2019-02-09 16:06

MOT test number

561992948760

Result

✓ Passed

Advice Rear Inner Tyre worn close to legal limit/worn on edge Both side (5.2.3 (e))**Advice** Nearside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Advice** Fuel Nick pipe slightly corroded**Advice** Nearside Rear Anti-roll bar modified but not seriously weakened D boshes (5.3.3 (c) (i))**MOT #17**

2019-02-08 18:54

MOT test number

230111303439

Result

✗ Failed

MAJOR Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Fuel Nick pipe slightly corroded**Advice** Nearside Rear Anti-roll bar modified but not seriously weakened D boshes (5.3.3 (c) (i))**MAJOR** Offside Front Headlamp aim not tested (4.1.2 (b))**MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Advice** Rear Inner Tyre worn close to legal limit/worn on edge Both side (5.2.3 (e))

**MOT #16** 2018-04-04 10:46**MOT test number** 891538608327**Result** ✓ Passed**MOT #15** 2018-04-03 11:48**MOT test number** 759473597587**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on main beam (1.7.5a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #14** 2018-03-29 14:27**MOT test number** 195090888299**Result** ✗ Failed**Fail** Offside Rear Trailing arm worn and seriously weakened (2.4.G.1)**Fail** Nearside Rear Trailing arm worn and seriously weakened (2.4.G.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #13** 2018-03-29 09:36**MOT test number** 210569437201**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #12** 2017-03-30 13:58**MOT test number** 152054612826**Result** ✓ Passed

**MOT #11** 2016-03-17 14:05**MOT test number** 466477288480**Result** ✓ Passed**Advice** Child seat fitted**MOT #10** 2016-03-17 08:31**MOT test number** 704784700029**Result** ✗ Failed**Advice** Child seat fitted**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #9** 2015-03-30 16:35**MOT test number** 599289485089**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2014-01-10 11:50**MOT test number** 736340514070**Result** ✓ Passed**Notice** Orniment fitted to bonnet**MOT #7** 2012-11-07 12:32**MOT test number** 465202712483**Result** ✓ Passed

**MOT #6** 2011-10-26 11:50**MOT test number** 999839091205**Result** ✓ Passed**Notice** Oil leak under engine.**MOT #5** 2010-10-19 11:00**MOT test number** 382912190203**Result** ✓ Passed**MOT #4** 2009-10-20 12:57**MOT test number** 873023799266**Result** ✓ Passed**Notice** Small cracks in off-side rear tyre outer wall**Notice** Near-side rear tyre bald on very inner edge**MOT #3** 2008-10-24 12:30**MOT test number** 951048898220**Result** ✓ Passed**MOT #2** 2008-03-03 13:41**MOT test number** 113913768023**Result** ✓ Passed**Notice** Nail in nearside rear tyre**MOT #1** 2007-03-13 08:59**MOT test number** 542542577098**Result** ✓ Passed



Tax & MOT check

×
Untaxed

Tax expired:
1 July 2022

×
MOT

Expired:
8 February 2022

Tax status

Expired at 1 July 2022

Days left

669 days too late

MOT expiry date

8 February 2022

Full MOT history[See MOT history](#)

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	Y888AJW
Plate since	2024-03-29
Current registration	Y888AJW
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-01-23
Last registration	2021-02-09
Complete history	See info



Registration #1	2004-01-23	15 mi
Registration #2	2007-03-13	20.104 mi
Registration #3	2008-03-03	26.924 mi
Registration #4	2008-10-24	28.950 mi
Registration #5	2009-10-20	34.536 mi
Registration #6	2010-10-19	38.377 mi
Registration #7	2011-10-26	40.512 mi
Registration #8	2012-11-07	42.473 mi
Registration #9	2014-01-10	48.827 mi
Registration #10	2015-03-30	55.531 mi
Registration #11	2016-03-17	67.579 mi
Registration #12	2016-03-17	67.579 mi
Registration #13	2016-03-17	67.579 mi
Registration #14	2016-03-17	67.579 mi
Registration #15	2016-03-17	67.579 mi
Registration #16	2016-03-17	67.579 mi
Registration #17	2016-03-17	67.579 mi
Registration #18	2016-03-17	67.579 mi
Registration #19	2016-03-17	67.579 mi
Registration #20	2016-03-17	67.579 mi
Registration #21	2016-03-17	67.579 mi
Registration #22	2016-03-17	67.579 mi
Registration #23	2016-03-17	67.579 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2
Engine number	0404220817016B