



General information

Make	LAND ROVER
Model	RANGE ROVER SDV8 VOGUE
Colour	Silver
Year of manufacture	2013
Top speed	135 mph
0 - 100 km/h	6.9 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	250 kW / 341 HP / 339 BHP
Max. torque	700 Nm at 1.700 rpm
Engine capacity	4.367 cc
Cylinders	8
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	37.2 mpg
Consumption combined	32.5 mpg
CO2 emission	229 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-09-30
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-11-15
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	19
Total items failed	2

MOT #9	2023-11-16 12:34
MOT test number	405762342218
Result	✓ Passed
Next expiry date	2024-11-15
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2022-10-26 10:47
MOT test number	862296530959
Result	✓ Passed

MOT #7	2021-10-26 11:42
MOT test number	485287257785
Result	✓ Passed

MOT #6	2021-10-11 13:40
MOT test number	562084879786
Result	✓ Passed
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear Upper Brake pipe corroded, covered in grease or other material Pipes across rear axle corroding (1.1.11 (c))



MOT #5	2020-09-28 18:01
MOT test number	153008133462
Result	✓ Passed
MOT #4	2019-09-26 08:42
MOT test number	593213811863
Result	✓ Passed
MOT #3	2018-09-26 16:05
MOT test number	527702162495
Result	✓ Passed
Advice	Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords Sidewall (5.2.3 (d) (i))
Advice	OSR tyre worn on inner and outer edges
Advice	Water in OSR light unit

**MOT #2**

2018-02-22 09:26

**MOT test number**

557658938433

**Result****✗ Failed****Fail**

Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice**

Nearside Rear flex brake hose / steel pipe section corroded

**Advice**

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice**

Offside Front tyre feathering on inner edge

**Advice**

Front Brake pad(s) wearing thin (3.5.1g)

**Advice**

Offside Front tyre side wall has a cut but it is not exposing cords

**Advice**

Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement inner (2.4.G.2)

**Advice**

Offside Rear flex brake hose / steel pipe section corroded

**Advice**

Offside Front tyre has nail / screw in

**Fail**

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice**

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice**

Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement inner (2.4.G.2)

**Advice**

Offside Rear tyre feathering on outer and inner edges

**MOT #1**

2017-02-24 14:42

**MOT test number**

363723595137

**Result****✓ Passed****Advice**

Too clean to register on smoke test



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
15 November 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	15 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	L
<b>Single payment (12 months)</b>	£ 675,00,-
<b>Single six month payment</b>	£ 371,25,-
<b>Total payable by 12 monthly instalments</b>	£ 708,75,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-03-13
Last registration	2023-11-16
Complete history	<a href="#">See info</a>



Registration #1	2013-03-13	25 mi
Registration #2	2017-02-24	47.167 mi
Registration #3	2018-02-22	48.323 mi
Registration #4	2018-09-26	48.509 mi
Registration #5	2019-09-26	53.174 mi
Registration #6	2020-09-28	56.436 mi
Registration #7	2023-11-16	56.436 mi
Registration #8	2023-11-16	56.436 mi
Registration #9	2023-11-16	56.436 mi
Registration #10	2023-11-16	56.436 mi
Registration #11	2023-11-16	56.436 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	84%
Pedestrian	63%
Safety systems	86%
Overall rating	84%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2220 mm
Height	1867 mm
Length	4998 mm
Wheel base	2922 mm
Kerb weight	2360 kg
Max. allowed weight	3200 kg

Additional information

Fuel tank capacity	105 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0029133448DT