



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | NISSAN |
| Model | MICRA ACENTA |
| Colour | White |
| Year of manufacture | 2015 |
| Top speed | 106 mph |
| 0 - 60 mph | 13.7 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 79 BHP |
| Max. torque | 110 Nm at 4.000 rpm |
| Engine capacity | 1.198 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 46.3 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 115 g/km |
| CO2 label | C |







Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-29 |
| Pictures | 20 |
| Listing price | View report |



source: yesauto.com



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-05-02 |
| MOT pass rate | 88 % |
| MOT passed | 7 |
| Failed MOT tests | 1 |
| Total advice items | 18 |
| Total items failed | 2 |

| | |
|------------------|------------------------------------------------------|
| MOT #8 | 2024-04-18 12:22 |
| MOT test number | 630719735546 |
| Result | ✓ Passed |
| Next expiry date | 2025-05-02 |
| Minor | Front Windscreen wiper blade defective (3.4 (b) (i)) |

| | |
|-----------------|---------------------------------------------------------------------------------------------------------------------------------------------|
| MOT #7 | 2023-04-27 08:25 |
| MOT test number | 860913081170 |
| Result | ✓ Passed |
| Minor | Nearside Windscreen wiper blade defective smearing screen (3.4 (b) (i)) |
| Advice | Offside Front Brake disc worn, but not excessively disc worn/lipped (1.1.14 (a) (i)) |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt |
| Advice | Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement wishbone front bush un bonding (5.3.4 (a) (i)) |
| Minor | Offside Windscreen wiper blade defective smearing screen (3.4 (b) (i)) |
| Advice | Nearside Front Brake disc worn, but not excessively disc worn/lipped (1.1.14 (a) (i)) |
| Advice | Offside Front Service brake binding but not excessively (1.2.1 (f)) |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt |
| Advice | Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement wishbone front bush un bonding (5.3.4 (a) (i)) |

**MOT #6** 2022-05-03 13:03**MOT test number** 577979492764**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Items removed from driver's view prior to test**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2021-03-10 07:15**MOT test number** 140361234136**Result** ✓ Passed**MOT #4** 2020-10-07 11:03**MOT test number** 209642093197**Result** ✓ Passed**Advice** Clutch slipping**MOT #3** 2019-11-28 08:48**MOT test number** 978973718618**Result** ✓ Passed**Advice** TPMS (tyre pressure monitoring system) light illuminated on dashboard**Minor** Windscreen wiper blade defective both front wipers smear slightly (3.4 (b) (i))**MOT #2** 2018-11-29 11:59**MOT test number** 482017500854**Result** ✓ Passed



| | |
|-----------------|------------------------------------------------------------------------------------------|
| MOT #1 | 2018-11-29 10:57 |
| MOT test number | 949944120673 |
| Result | ✗ Failed |
| Fail | Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |
| Fail | Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
2 May 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 March |
| Days left | 307 |
| MOT expiry date | 2 May 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|------------------------------------------------|----------------|
| Vehicle class | 48 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this NISSAN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-09-29 |
| Current registration | ***** |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 10 |
| First mileage registration | 2015-11-30 |
| Last registration | 2024-04-18 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2015-11-30 | 17 mi |
| Registration #2 | 2018-11-29 | 19.213 mi |
| Registration #3 | 2018-11-29 | 19.213 mi |
| Registration #4 | 2019-11-28 | 28.267 mi |
| Registration #5 | 2020-10-07 | 32.289 mi |
| Registration #6 | 2020-10-07 | 32.289 mi |
| Registration #7 | 2020-10-07 | 32.289 mi |
| Registration #8 | 2020-10-07 | 32.289 mi |
| Registration #9 | 2020-10-07 | 32.289 mi |
| Registration #10 | 2020-10-07 | 32.289 mi |

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 84% |
| Children | 79% |
| Pedestrian | 58% |
| Safety systems | 57% |
| Overall rating | 75% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1665 mm |
| Height | 1520 mm |
| Length | 3825 mm |
| Wheel base | 2450 mm |
| Kerb weight | 925 kg |
| Max. allowed weight | 1425 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 41 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|---------------|---------|
| Engine number | 820374B |
|---------------|---------|