



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	White
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-06
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-05
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	19
Total items failed	3

MOT #11	2023-06-29 14:16
MOT test number	996821528992
Result	✓ Passed
Next expiry date	2024-07-05
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Knock noise from steering
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10	2022-07-05 09:34
MOT test number	416602544475
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened large lip & rusty (1.1.14 (a) (ii))
Advice	Knocking in steering when rocked

MOT #9	2021-07-06 15:54
MOT test number	142672600471
Result	✓ Passed

**MOT #8** 2021-01-14 09:33**MOT test number** 505095591562**Result** ✓ Passed**MOT #7** 2019-12-31 14:09**MOT test number** 576159624449**Result** ✓ Passed

- Advice** Power steering component has slight seepage from a component steering rack (2.1.5 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #6 2019-12-31 13:05**MOT test number** 522511028990**Result** ✗ Failed

- Fail** Reversing lamp inoperative (4.6.1 (a))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Power steering component has slight seepage from a component steering rack (2.1.5 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #5 2019-01-11 15:15**MOT test number** 930928527917**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust heat shield clip broken but shield still secure

**MOT #4** 2019-01-11 14:03**MOT test number** 749670303124**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Exhaust heat shield clip broken but shield still secure**Fail** Reversing lamp inoperative (4.6.1 (a))**MOT #3** 2018-01-13 09:17**MOT test number** 200626326733**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit 3mm, worn inner edge (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit 3mm, worn inner edge (4.1.E.1)**MOT #2** 2017-01-03 12:43**MOT test number** 763525957694**Result** ✓ Passed**MOT #1** 2016-01-29 10:42**MOT test number** 378393758887**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
5 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	VU13MVT
Plate since	2019-09-29
Current registration	VU13MVT
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-03-19
Last registration	2023-06-29
Complete history	See info



Registration #1	2013-03-19	22 mi
Registration #2	2016-01-29	11.744 mi
Registration #3	2017-01-03	15.742 mi
Registration #4	2018-01-13	25.800 mi
Registration #5	2019-01-11	38.238 mi
Registration #6	2019-01-11	38.238 mi
Registration #7	2019-12-31	47.801 mi
Registration #8	2019-01-11	38.238 mi
Registration #9	2019-01-11	38.238 mi
Registration #10	2019-01-11	38.238 mi
Registration #11	2019-01-11	38.238 mi
Registration #12	2019-01-11	38.238 mi
Registration #13	2019-01-11	38.238 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ