





General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI BLUEMOTION TECHNOLOGY
Colour	Black
Year of manufacture	-
Top speed	126 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg



Internet history Entry 1 Date 2021-10-20 Pictures 2 Listing price View report



source: autotrader.co.uk



MOT history

МОТ #9	2021-09-06 14:52
MOT test number	276346247421
Result	✓ Passed
Next expiry date	2022-09-08
Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice Rear wiper bald Does not clear windscreen effectively	
Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))	

МОТ #8	2021-09-04 09:48
MOT test number	225665905109
Result	🗙 Failed
Advice Rear wiper bald Does not clear windscreen effectively	
MAJOR Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))	
Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))	

MOT #7	2020-09-09 10:51
MOT test	number 451877626938
Result	✓ Passed
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Nail in tyre
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6		2019-05-14 13:23
MOT test	number	551267464826
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))	





MOT #5		2019-05-14 11:14
MOT test	number	192569908919
Result		🗙 Failed
MAJOR	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
MAJOR (5.2.3 (d)	Nearside Rear Tyre has a cut in excess of the requirements deep enough to re (i))	ach the ply or cords
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))	
MOT #4		2018-05-15 11.50

MOT #4	2018-05-15 11:50
MOT test number	319213564826
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)	

MOT #3	2017-05-13 10:22
MOT test number	360518074842
Result	✓ Passed

MOT #2	2017-05-13 09:42
MOT test number	482171626234
Result	🗙 Failed
Fail Offside Front Obligatory mirror seriously obscured affecting the rear view (8.1.2a)	

MOT #1	2016-04-28 13:51
MOT test number	297831911610
Result	✓ Passed





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FETT
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE .
Category	AM
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.000

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-05-17
Last registration	2021-09-06
Complete history	<u>See info</u>



Registration #1	2013-05-17	15 mi
Registration #2	2016-04-28	43.759 mi
Registration #3	2017-05-13	51.256 mi
Registration #4	2017-05-13	51.256 mi
Registration #5	2018-05-15	59.781 mi
Registration #6	2019-05-14	71.263 mi
Registration #7		11.222 mi
Registration #8		11.222 est
Registration #9		11.222 est
Registration #10		11.222 est
Registration #11		11.222 mi

More info \rightarrow





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating

CarCheck.co.uk

Video

see crash video



Dimensions & weight	
Width	1794 mm
Height	1674 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1582 kg
Max. allowed weight	2260 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	CFHC526431