



report date: 2024-03-29

General information

Make	NISSAN
Model	PRIMERA S
Colour	Silver
Year of manufacture	-
Top speed	121 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	163 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	38.2 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-08-29
Pictures	9
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-28
Pictures	11
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history****MOT #14**

2022-11-03 14:51

MOT test number

643045351364

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Rear Service brake has no recorded effort at a wheel (1.2.1 (a) (ii))
- Fail** Brake performance not tested (1.2.1 (g))
- Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Emissions not tested (8.2.1.2 (d))
- Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Boot lid cannot be secured in the closed position (6.2.1 (e))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #13** 2021-03-03 11:58**MOT test number** 334236960655**Result** ✓ Passed**Advice** Nearside Front Coil spring worn (5.3.1 (b) (i))**MOT #12** 2020-02-22 15:38**MOT test number** 495023089420**Result** ✓ Passed**MOT #11** 2019-03-16 17:17**MOT test number** 693376863674**Result** ✓ Passed**Advice** Front Suspension arm corroded but not seriously weakened (Bothside) (5.3.3 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**MOT #10** 2014-05-19 15:59**MOT test number** 535429334129**Result** ✓ Passed

**MOT #9** 2014-05-19 09:07**MOT test number** 506099634167**Result** ✗ Failed**Fail** Horn not working (1.6.2a)**Fail** Offside Stop lamp not working (1.2.1b)**Notice** Parking brake just on limit**Fail** Front brake application uneven (3.7.B.2)**MOT #8** 2013-05-20 15:13**MOT test number** 805060543177**Result** ✓ Passed**MOT #7** 2013-05-20 11:06**MOT test number** 645270943167**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**MOT #6** 2012-05-28 16:49**MOT test number** 219689642117**Result** ✓ Passed**MOT #5** 2012-05-28 11:04**MOT test number** 716189342184**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Nearside rear tyre close to limit**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #4** 2011-05-16 12:36**MOT test number** 458396931192**Result** ✓ Passed**MOT #3** 2011-05-16 09:10**MOT test number** 629456431114**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2010-05-10 17:21**MOT test number** 592570530185**Result** ✓ Passed**MOT #1** 2009-05-22 09:47**MOT test number** 473282349127**Result** ✓ Passed



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-05-26
Last registration	2022-11-03
Complete history	See info



Registration #1	2006-05-26	25 mi
Registration #2	2009-05-22	28.794 mi
Registration #3	2010-05-10	38.007 mi
Registration #4	2011-05-16	49.359 mi
Registration #5	2011-05-16	49.359 mi
Registration #6	2012-05-28	60.083 mi
Registration #7	2012-05-28	60.083 mi
Registration #8	2013-05-20	99.903 mi
Registration #9	2013-05-20	70.018 mi
Registration #10	2013-05-20	70.018 mi
Registration #11	2013-05-20	70.018 mi
Registration #12	2013-05-20	70.018 mi
Registration #13	2013-05-20	70.018 mi
Registration #14	2013-05-20	70.018 mi
Registration #15	2013-05-20	70.018 mi
Registration #16	2013-05-20	70.018 mi
Registration #17	2013-05-20	70.018 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1488 mm
Length	4567 mm
Wheel base	2680 mm
Kerb weight	1361 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	451317