





report date: 2024-03-29

### General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM DCI
Colour	Blue
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	12.3 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/12



## Internet history

Entry 2	
Date	2022-11-26

Pictures 0

Listing price <u>View report</u>

#### source: autotrader.co.uk

#### Entry 1

Date	2021-09-09
Pictures	0
Listing price	<u>View report</u>

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-10-26
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	11
Total items failed	9

MOT #13	2023-10-27 10:48
MOT test number	375638925075
Result	✓ Passed
Next expiry date	2024-10-26

MOT #12	2022-10-26 15:15
MOT test number	454171946140
Result	✓ Passed

MOT #:	<b>11</b> 2022-1	10-26 10:12
MOT te	est number 314	383024071
Result		<b>X</b> Failed
Fail	Offside Front Windscreen wiper blade missing (3.4 (b) (ii))	
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

MOT #10	2021-09-09 17:36
MOT test number	583833696973
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



MOT test number

Result

Result

Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail

Front Outer Track rod end ball joint has excessive play both (2.1.3 (b) (i))

MOT #8

MOT test number

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number

Result

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Anti-roll bar ball joint has slight play drop link (5.3.4 (a) (i))

**MOT** #6 2020-03-10 09:21 947510460974 **MOT** test number Result × Failed Fail Brake fluid contaminated (1.8 (a)) Offside Front Anti-roll bar ball joint has slight play drop link (5.3.4 (a) (i)) **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt Advice **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Rear Service brake excessively binding (1.2.1 (f))

CarCheck.co.uk page 4/12



**MOT #5** 2018-10-30 15:39

**MOT test number** 378629941395

**MOT #4** 2017-12-20 14:49

MOT test number 312865513987

**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)

MOT #3 2017-12-20 11:51

**MOT test number** 333940048701

Result X Failed

**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)

**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #2 2016-10-11 11:20

**MOT test number** 804972881205

Result \square Passed

**MOT #1** 2015-10-28 00:00

**MOT test number** 657341508092

**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened has been getting hot

(3.5.1i)

CarCheck.co.uk page 5/12



#### Tax & MOT check





Tax status	Expired at 2 September
Days left	970 days too late
MOT expiry date	26 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	historv
OWNER	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

•	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
manage of the same	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	AK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-11-29
Last registration	2023-10-27
Complete history	See info



Registration #1	2012-11-29	14 mi
Registration #2	2015-10-28	54.972 mi
Registration #3	2016-10-11	64.802 mi
Registration #4	2017-12-20	78.727 mi
Registration #5	2017-12-20	78.727 mi
Registration #6	2018-10-30	82.170 mi
Registration #7	2020-03-10	96.468 mi
Registration #8	2020-03-10	96.468 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 mi
Registration #16		10.777 au

More info >

page 11/12 CarCheck.co.uk



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1808 mm
Height	1471 mm
Length	4295 mm
Wheel base	2703 mm
Kerb weight	1215 kg
Max. allowed weight	1813 kg

## Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

**Engine number** D096392