



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	Blue
Year of manufacture	2015
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-22
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



## MOT history

MOT expiry date	2024-10-12
MOT pass rate	55 %
MOT passed	6
Failed MOT tests	5
Total advice items	30
Total items failed	2

## MOT #11 2023-10-13 14:39

MOT test number 238133098863

Result ✓ Passed

Next expiry date 2024-10-12

- Advice** Sub-frame corroded but not seriously weakened front/rear (5.3.3 (b) (i))
- Advice** Suspension arm corroded but not seriously weakened o/s n/s front/rear (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

## MOT #10 2023-10-11 14:56

MOT test number 472704488969

Result ✗ Failed

- MAJOR** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Advice** Suspension arm corroded but not seriously weakened o/s n/s front/rear (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Sub-frame corroded but not seriously weakened front/rear (5.3.3 (b) (i))

**MOT #9**

2022-09-12 11:07

**MOT test number**

494790897562

**Result**

✓ Passed

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Getting close (5.2.3 (e))

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Rear Suspension arm corroded but not seriously weakened N/S & O/S (5.3.3 (b) (i))

**Advice** Nearside Front Side repeater has slight damage

**MOT #8**

2022-09-12 10:10

**MOT test number**

853477518563

**Result**

✗ Failed

**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**Advice** Rear Suspension arm corroded but not seriously weakened N/S & O/S (5.3.3 (b) (i))

**Advice** Nearside Front Side repeater has slight damage

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Getting close (5.2.3 (e))

**MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #7**

2021-08-12 16:04

**MOT test number**

219826537928

**Result**

✗ Failed

**MAJOR** Front Brake disc significantly and obviously worn both (1.1.14 (a) (i))

**MOT #6** 2021-04-10 10:40**MOT test number** 827171830081**Result** ✓ Passed**MOT #5** 2020-03-25 11:39**MOT test number** 253055511681**Result** ✓ Passed**MOT #4** 2020-03-25 11:39**MOT test number** 543584070095**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too far to the left (4.1.2 (a))**MOT #3** 2019-04-06 12:05**MOT test number** 252598279177**Result** ✓ Passed**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #2** 2018-03-28 07:15**MOT test number** 910353987346**Result** ✓ Passed**MOT #1** 2018-03-24 10:06**MOT test number** 381793507072**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Wheel nut(s) missing (4.2.A.1e)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
12 October 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	12 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-04-10
Last registration	2023-10-13
Complete history	<a href="#">See info</a>



Registration #1	2015-04-10	16 mi
Registration #2	2018-03-24	46.801 mi
Registration #3	2018-03-28	46.950 mi
Registration #4	2019-04-06	64.951 mi
Registration #5	2020-03-25	80.613 mi
Registration #6	2020-03-25	80.613 mi
Registration #7	2021-04-10	93.552 mi
Registration #8	2023-10-13	115.277 mi
Registration #9	2023-10-13	115.277 mi
Registration #10	2023-10-13	115.277 mi
Registration #11	2023-10-13	115.277 mi
Registration #12	2023-10-13	115.277 mi
Registration #13	2023-10-13	115.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FDFZ359220