



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	RCZ THP SPORT
Colour	White
Year of manufacture	2013
Top speed	133 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 2

Date	2021-09-11
Pictures	19
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-09-09
Pictures	19
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-03-20
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	18
Total items failed	13

MOT #12	2024-03-05 15:23
MOT test number	929889676712
Result	✓ Passed
Next expiry date	2025-03-20

MOT #11	2024-02-28 16:27
MOT test number	685800826290
Result	✗ Failed
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Front Headlamp aim too high Bulb fitted incorrectly (4.1.2 (a))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #10	2023-03-17 14:52
MOT test number	307708612983
Result	✓ Passed
Advice	Oil leak, but not excessive Engine oil leak. (8.4.1 (a) (i))

**MOT #9**

2022-03-21 09:05

**MOT test number**

176646090199

**Result**

✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #8**

2022-03-04 14:52

**MOT test number**

292832344454

**Result**

✗ Failed

- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play Drop link (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush (5.3.4 (a) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

**MOT #7** 2021-03-05 16:04**MOT test number** 760637590137**Result** ✓ Passed**MOT #6** 2020-02-13 10:55**MOT test number** 380199665793**Result** ✓ Passed**MOT #5** 2020-02-13 10:55**MOT test number** 709498956928**Result** ✗ Failed**Pass with rectification** Front Undertray likely to become detached (6.2.1 (a) (ii))**Pass with rectification** Front Windscreen washer not working (3.5 (a))**MOT #4** 2019-02-08 15:44**MOT test number** 355830093783**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2019-02-08 14:54**MOT test number** 545466689524**Result** ✗ Failed**Fail** Offside Front Lower Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Lower Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))



MOT #2	2018-02-17 14:20
MOT test number	323354420383
Result	✓ Passed
Advice	Nearside Rear tyre tread low

MOT #1	2017-03-01 12:33
MOT test number	994197521470
Result	✓ Passed
Advice	Both Near Side tyres have tyre wall damage.



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
20 March 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	20 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	YB13XHO
Plate since	2019-03-28
Current registration	YB13XHO
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-07-31
Last registration	2024-03-05
Complete history	<a href="#">See info</a>



Registration #1	2013-07-31	18 mi
Registration #2	2017-03-01	29.265 mi
Registration #3	2018-02-17	40.706 mi
Registration #4	2019-02-08	54.504 mi
Registration #5	2019-02-08	54.504 mi
Registration #6	2020-02-13	69.558 mi
Registration #7	2020-02-13	69.558 mi
Registration #8	2021-03-05	77.870 mi
Registration #9	2022-03-05	77.870 mi
Registration #10	2023-03-05	77.870 mi
Registration #11	2024-03-05	77.870 mi
Registration #12	2024-03-05	77.870 mi
Registration #13	2024-03-05	77.870 mi
Registration #14	2024-03-05	77.870 mi
Registration #15	2024-03-05	77.870 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2107 mm
Height	1362 mm
Length	4290 mm
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2

Engine number FJBS1742466