





report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 SWB P/V HDI 90
Colour	White
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-10-10

Pictures 43

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2024-09-05
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	8
Total items failed	9

MOT #14	2023-08-10 13:00
MOT test number	198587484273
Result	✓ Passed
Next expiry date	2024-09-05
Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #13	2022-09-06 14:09
MOT test number	346278867968
Result	✓ Passed
Advice Offside Front Macpherson strut corroded but not seriously weakened (5.3.3	3 (b) (i))

MOT #12	2021-12-21 11:57
MOT test number	205558164369
Result	✓ Passed
Advice Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))	

MOT #11	2021-01-14 13:42
MOT test number	207038902191
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #10	2019-04-10 11:45
MOT test number	771384616555
Result	✓ Passed
MOT #9	2019-04-09 10:45
MOT test number	224009578739
Result	× Failed
Fail Hazard warning switch inoperative (4.4.2 (a) (ii))	

MOT #8	2018-03-28 07:56
MOT test number	505211869500
Result	✓ Passed
MOT #7	2018-03-23 09:37
MOT test number	652089618614
Result	× Failed
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #6	2016-09-28 15:19
MOT test number	740141024319
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #5 2016-09-28 12:45

MOT test number 929633772927

Result X Failed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #4 2016-09-15 16:13

MOT test number 883915823841

Result X Failed

Fail Offside Inner Brake lining(s) less than 1.5 mm thick (3.5.1g)

Fail Offside Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Offside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Offside Registration plate lamp not working (1.1.C.1d)

MOT #3 2015-08-20 10:12

MOT test number 691594533939

Result
✓ Passed

MOT #2 2014-07-14 10:33

MOT test number 866245894147

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1 2013-07-18 15:38 MOT test number 385119893144

Result ✓ Passed

Notice Nearside side door will not open

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Days left 126

MOT expiry date 5 September 2024

Full MOT history See MOT history

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



factor scincol

ND10VDA

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this CITROEN had different number plates.

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Pinance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-08-09
Last registration	2023-08-10
Complete history	See info



Registration #1	2010-08-09	6 mi
Registration #2	2013-07-18	43.172 mi
Registration #3	2014-07-14	87.278 mi
Registration #4	2015-08-20	60.853 mi
Registration #5	2016-09-15	68.285 mi
Registration #6	2016-09-28	68.519 mi
Registration #7	2016-09-28	68.519 mi
Registration #8	2018-03-23	79.240 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.177 au
Registration #15		11.777 es

7070.70.70

More info >

77.777 86

CarCheck.co.uk page 12/13



ND10VDA report date: 2024-03-28

Dimensions & weight

Width	2194 mm
Height	1942 mm
Length	4805 mm
Wheel base	3000 mm
Kerb weight	1661 kg
Max. allowed weight	2661 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	JBBY0037978

CarCheck.co.uk page 13/13