



report date: 2024-03-28

General information

Make	KIA
Model	SORENTO XE
Colour	Silver
Year of manufacture	-
Top speed	113 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	392 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	28.2 mpg
Consumption extra urban	42.2 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-26
Pictures	34
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history****MOT #17** 2023-01-30 17:41**MOT test number** 927237387633**Result** ✓ Passed**Next expiry date** 2024-01-30**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Prop shaft joint worn, but not excessively transfer shaft (6.1.7 (c) (i))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #16** 2022-01-31 11:46**MOT test number** 514869497179**Result** ✓ Passed**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**MOT #15** 2021-01-04 08:48**MOT test number** 578517999808**Result** ✓ Passed**MOT #14** 2020-01-21 12:14**MOT test number** 889770539624**Result** ✓ Passed**MOT #13** 2019-05-16 14:47**MOT test number** 407279098367**Result** ✓ Passed

**MOT #12**

2019-05-13 14:00

**MOT test number**

420245217951

**Result****✗ Failed**

- Fail** Offside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Rear Brake pipe excessively corroded of front to rear above tank (1.1.11 (c))

**MOT #11**

2018-12-22 11:59

**MOT test number**

350470939372

**Result****✓ Passed**

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #10	2017-12-02 09:37
MOT test number	361165972398
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Advice	Rust forming on exhaust system
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #9	2016-12-16 09:30
MOT test number	132946786248
Result	✓ Passed
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)
Advice	Long handbrake travel
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
Advice	Rust forming on exhaust system
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Small chips in windscreen

**MOT #8** 2016-12-16 09:30**MOT test number** 867395908193**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Small chips in windscreen**Advice** Long handbrake travel**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Rust forming on exhaust system**MOT #7** 2015-12-14 10:27**MOT test number** 541726950014**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Brake fluid low**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2014-12-16 14:11**MOT test number** 335930054352**Result** ✓ Passed



MOT #5	2014-12-16 14:11
MOT test number	689970354326
Result	✗ Failed
<div>Pass with rectification</div> Offside Stop lamp not working (1.2.1b)	
MOT #4	2014-01-17 09:43
MOT test number	726197314084
Result	✓ Passed
MOT #3	2013-01-22 14:47
MOT test number	156882023041
Result	✓ Passed
MOT #2	2012-09-07 09:55
MOT test number	769421752214
Result	✓ Passed
MOT #1	2011-09-10 12:12
MOT test number	655873851211
Result	✓ Passed



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-04-01
Last registration	2023-01-30
Complete history	<a href="#">See info</a>



Registration #1	2008-04-01	20 mi
Registration #2	2011-09-10	27.920 mi
Registration #3	2012-09-07	34.053 mi
Registration #4	2013-01-22	36.192 mi
Registration #5	2014-01-17	58.922 mi
Registration #6	2014-12-16	73.345 mi
Registration #7	2015-12-14	82.622 mi
Registration #8	2016-12-16	93.095 mi
Registration #9	2016-12-16	93.095 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi
Registration #18	2019-05-29	95.377 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1885 mm
Height	1805 mm
Length	4590 mm
Wheel base	2710 mm
Max. allowed weight	2640 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

D4CB729452