



report date: 2024-03-29

General information

Make	LAND ROVER
Model	FREELANDER SD4 GS
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 100 km/h	9.5 seconds
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 kW / 191 HP / 190 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-06-28
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-08-31
<b>MOT pass rate</b>	88 %
<b>MOT passed</b>	7
<b>Failed MOT tests</b>	1
<b>Total advice items</b>	10
<b>Total items failed</b>	1

**MOT #8** 2023-09-01 15:37**MOT test number** 208277580861**Result** ✓ Passed**Next expiry date** 2024-08-31**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**MOT #7** 2022-08-16 14:27**MOT test number** 342880134711**Result** ✓ Passed**MOT #6** 2021-08-23 13:09**MOT test number** 266891882192**Result** ✓ Passed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2021-08-23 08:25**MOT test number** 976990705697**Result** ✗ Failed**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2020-08-27 08:18**MOT test number** 155432837895**Result** ✓ Passed**Advice** Central Rear Outer Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge down to 2mm on outer edge (5.2.3 (e))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2019-08-07 09:13**MOT test number** 253011158945**Result** ✓ Passed**Advice** Unable to fully inspect due to covers and shields**MOT #2** 2018-09-11 14:50**MOT test number** 177912831016**Result** ✓ Passed**MOT #1** 2017-09-11 08:38**MOT test number** 134991753057**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
31 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	31 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >





Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-09-01
Last registration	2023-09-01
Complete history	<a href="#">See info</a>



Registration #1	2014-09-01	23 mi
Registration #2	2017-09-11	42.959 mi
Registration #3	2018-09-11	48.937 mi
Registration #4	2019-08-07	56.424 mi
Registration #5	2020-08-27	65.702 mi
Registration #6	2021-08-27	75.000 mi
Registration #7	2022-08-27	85.000 mi
Registration #8	2023-08-27	95.000 mi
Registration #9	2024-03-29	105.000 mi
Registration #10	2024-03-29	115.000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2005 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1745 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	DZ784181354224DT