





report date: 2024-03-29

### General information

Make	FORD
Model	FOCUS C-MAX ZETEC
Colour	Blue
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	4 speed automatic

## Engine & fuel consumption

Power	143 BHP
Max. torque	185 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

### Entry 1


Date 2021-06-19

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

### **MOT** history

**MOT #17** 2021-07-06 10:42

MOT test number 451281602072

**Result** ✓ Passed

Next expiry date 2022-07-05

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #16 2020-09-22 12:03

**MOT test number** 993063925471

Result \( \sqrt{Passed} \)

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #15** 2019-09-23 14:55

**MOT test number** 151625333029

Result \( \sqrt{Passed} \)

**MOT #14** 2019-09-23 08:50

MOT test number 270769148332

Result X Failed

**MAJOR** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b)

(i))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #12

MOT test number

Result

Advice Child Seat fitted not allowing full inspection of adult belt

MOT test number

510475728559

Result

Advice MAN LIGHT ON AND VEHICLE STRUGGLED TO START

Advice Child Seat fitted not allowing full inspection of adult belt

Fail Electronic parking brake warning indicates a malfunction (3.1.7)

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #10

2016-09-23 15:51

MOT test number

522462118919

Result

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #9 2015-09-22 11:10

**MOT test number** 337998449370

Result \rightarrow Passed

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #8 2015-09-22 11:10

MOT test number 581824884091

**Result** X Failed

**Pass with rectification** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (1.1.C.1a)

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #7 2014-09-30 14:38

**MOT test number** 928233074215

**Result** ✓ Passed

MOT #6 2013-09-30 17:14

**MOT test number** 825293973231

**Result** ✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #5 2012-09-03 14:17

MOT test number 216707742264

Result \( \sqrt{Passed} \)

**Notice** Items removed from driver's view prior to test

**Notice** Engine covers fitted obscuring some components in the engine bay

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Notice** Under-trays fitted obscuring some underside components

CarCheck.co.uk page 5/12



report date: 2024-03-29

MOT #4 2011-09-27 10:18

**MOT test number** 387140471483

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #3 2010-10-01 14:40

MOT test number 892234070294

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2 2010-10-01 09:23

**MOT test number** 664254870282

Result X Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #1** 2009-09-25 11:20

**MOT test number** 292688069240

Result \( \sqrt{Passed} \)

Advice Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Notice** Both front tyres low inner edge

CarCheck.co.uk page 6/12



report date: 2024-03-29

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 8/12



report date: 2024-03-29

# Owner history For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <a href="here">here</a>.

HIRTORY

More info >

### Plate changes

ober of plates

faste since

See in this check if this FORD had different number plates.

THE STATE OF THE S

UK UK

More info >



**YP56CXV** 

report date: 2024-03-29

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-10-18
Last registration	2021-07-06
Complete history	See info



Registration #1	2006-10-18	24 mi
Registration #2	2009-09-25	10.767 mi
Registration #3	2010-10-01	21.165 mi
Registration #4	2010-10-01	21.165 mi
Registration #5	2011-09-27	27.938 mi
Registration #6	2012-09-03	34.944 mi
Registration #7	2013-09-30	45.530 mi
Registration #8	2014-09-30	54.045 mi
Registration #9	2015-09-22	63.826 mi
Registration #10	2015-09-22	63.826 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 mg

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1420 kg
Max. allowed weight	1930 kg

### Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/1