



report date: 2024-03-28

General information

Make	NISSAN
Model	NAVARA DCI SE 4X4 SHR SWB DCB E4
Colour	Silver
Year of manufacture	2007
Top speed	105 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	169 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	32.8 mpg
Consumption combined	29.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-25
Pictures	18
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2022-08-26
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	53
Total items failed	6

MOT #17 2022-07-28 11:34

MOT test number 464591904622

Result ✗ Failed

DANGEROUS Offside Rear Vehicle structure has excessive corrosion which adversely affects braking or steering Leaf spring front mounting (6.1.1 (c) (ii))

Advice Offside Side repeater slightly discoloured (4.4.3 (a))

Advice Nearside Front Brake pipe corroded, covered in grease or other material Slightly corroded (1.1.11 (c))

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Side repeater slightly discoloured (4.4.3 (a))

Advice Offside Rear Brake pipe corroded, covered in grease or other material Covered in material (1.1.11 (c))

Advice Offside Front Brake pipe corroded, covered in grease or other material Slightly corroded (1.1.11 (c))

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #16**

2021-08-26 09:26

MOT test number

901186950647

Result

✓ Passed

- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Existing repairs to underside of vehicle untidy but appear ok
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Underside of vehicle undersealed best inspection carried out at time of test
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to cylinder (1.1.11 (c))

MOT #15

2021-05-26 05:51

MOT test number

514441946341

Result

✗ Failed

- MAJOR** Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis rail (5.3.6 (a) (i))
- Advice** Tow bar and mounting points getting corroded
- MAJOR** Suspension component mounting prescribed area excessively corroded significantly reducing structural strength both centre chassis rails (5.3.6 (a) (i))
- DANGEROUS** Offside Front Wheel bearing play so excessive that directional control is impaired (5.1.3 (a) (ii))
- MAJOR** Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
- Advice** Front and rear chassis rails, outriggers, crossmembers and chassis to body mounts getting corroded
- MAJOR** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis rail (5.3.6 (a) (i))
- Advice** Existing repairs to vehicle understructure ok

**MOT #14** 2020-08-27 14:15**MOT test number** 780417916997**Result** ✓ Passed**Advice** Chassis corroded and surface rust**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #13** 2019-08-10 08:40**MOT test number** 772307224082**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #12** 2018-08-10 14:28**MOT test number** 618332859397**Result** ✓ Passed**MOT #11** 2018-08-02 12:40**MOT test number** 808400846042**Result** ✗ Failed**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MAJOR** Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced n/s/r rear chasis (6.1.1 (c) (i))**MAJOR** Offside Rear Sub-frame corroded to the extent that the rigidity of the assembly is significantly reduced chasis leg (6.1.1 (c) (i))**MAJOR** Nearside Front Obligatory mirror missing (3.3 (a))**MAJOR** Fuel tank insecure fuel tank strap missing (6.1.3 (a) (i))**MAJOR** Offside Rear Sub-frame corroded to the extent that the rigidity of the assembly is significantly reduced o/s/r chasis (6.1.1 (c) (i))

**MOT #10** 2017-07-27 11:52**MOT test number** 861172865121**Result** ✓ Passed**MOT #9** 2016-08-03 11:26**MOT test number** 213783858258**Result** ✓ Passed**Advice** Nearside Front wheel bearing slight play**Advice** Nearside Front tyre worn on outer edge**MOT #8** 2015-08-05 13:54**MOT test number** 345707515421**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Windscreen cracked**Advice** Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**MOT #7** 2014-07-29 16:29**MOT test number** 487310614277**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Windscreen cracked but not in drivers view**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2014-07-23 13:17**MOT test number** 788034104254**Result** ✗ Failed**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Windscreen cracked but not in drivers view**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**MOT #5** 2013-07-30 14:45**MOT test number** 148921013265**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-02-15 10:58**MOT test number** 726586343028**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #3	2012-02-17 11:57
MOT test number	198968842043
Result	✓ Passed

MOT #2	2011-02-17 09:33
MOT test number	366668541001
Result	✓ Passed

MOT #1	2010-04-13 09:28
MOT test number	951593700126
Result	✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-04-02
Last registration	2022-07-28
Complete history	See info



Registration #1	2007-04-02	23 mi
Registration #2	2010-04-13	37.215 mi
Registration #3	2011-02-17	44.151 mi
Registration #4	2012-02-17	52.055 mi
Registration #5	2013-02-15	62.374 mi
Registration #6	2013-07-30	66.301 mi
Registration #7	2014-07-23	72.047 mi
Registration #8	2014-07-29	72.144 mi
Registration #9	2015-08-05	75.895 mi
Registration #10	2016-08-03	80.534 mi
Registration #11	2016-08-03	80.534 mi
Registration #12	2016-08-03	80.534 mi
Registration #13	2016-08-03	80.534 mi
Registration #14	2016-08-03	80.534 mi
Registration #15	2016-08-03	80.534 mi
Registration #16	2016-08-03	80.534 mi
Registration #17	2016-08-03	80.534 mi
Registration #18	2016-08-03	80.534 mi
Registration #19	2016-08-03	80.534 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	812097