





General information

Make	PEUGEOT
Model	207 ACTIVE
Colour	Blue
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	73 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	44.8 mpg
CO2 emission	145 g/km
CO2 label	F







Internet history

Entry 1

Date Pictures 2021-07-28

8

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-24
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	11
Total items failed	8

MOT #16	2024-01-25 14:27
MOT test number	293312331814
Result	✓ Passed
Next expiry date	2025-01-24
Minor Offside Registration plate lamp inoperative in the case of multiple lamps (i))	s or light sources (4.7.1 (b)

MOT #15	2024-01-25 10:05	
MOT test number	526867960582	
Result	🗙 Failed	
Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))		
FailOffside Rear Coil spring fractured or broken (5.3.1 (b) (i))		
Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt clip (6.1.7 (g) (ii))		
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or (i))	light sources (4.7.1 (b)	

MOT #14		2022-12-20 15:56
MOT test	number	283335443249
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



YW	61	Η	BJ
report o	late:	2024	-03-28

MOT #13	2022-12-20 11:59
MOT test number	803858493042
Result	🗙 Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Front Position lamp not working side (4.2.1 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2022-01-04 15:04
MOT test number	536253912075
Result	✓ Passed

MOT #11	2021-01-08 14:34
MOT test number	991824628447
Result	✓ Passed

MOT #	10	2021-01-08 09:07
MOT te	st number	851572398990
Result		🗙 Failed
Fail	Nearside Rear Wheel bearing so rough it is likely to overheat or break up (5.1	.3 (b) (ii))
Fail Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		

МОТ #9	2020-01-16 12:08
MOT test number	594385133313
Result	✓ Passed



YW61	HBJ
report date:	2024-03-28

MOT #8	2020-01-15 10:39
MOT test number	791007050812
Result	🗙 Failed
Minor Offside Position lamp incorrect colour (4.2.3 (a) (i))	
FailNearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Minor Nearside Position lamp incorrect colour (4.2.3 (a) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2019-03-26 16:27
MOT test number	406850547087
Result	✓ Passed

МОТ #6	2019-03-26 11:22
MOT test number	516497455257
Result	🗙 Failed
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Fail Windscreen washer not working (3.5 (a))	

MOT #5	2018-10-25 10:16
MOT test number	243289391834
Result	✓ Passed
МОТ #4	2017-10-23 09:17
MOT test number	972956808480

МОТ #3	2016-10-20 09:21
MOT test number	321275639769
Result	✓ Passed

🗸 Passed





MOT #2	2015-11-12 11:38
MOT test number	807934819412
Result	✓ Passed
Advice Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)	
MOT #1	2014-11-11 15:14
MOT test number	365385314387
Result	🗸 Passed



Tax & MOT check

Taxed	✓ MOT Expires: 24 January 2025
Tax status	Valid until 1 May
Days left MOT expiry date	368 24 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERM
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-11-18
Last registration	2024-01-25
Complete history	<u>See info</u>



Registration #1	2011-11-18	15 mi
Registration #2	2014-11-11	5.495 mi
Registration #3	2015-11-12	13.771 mi
Registration #4	2016-10-20	21.990 mi
Registration #5	2017-10-23	32.612 mi
Registration #6	2018-10-25	42.505 mi
Registration #7	2019-03-26	46.458 mi
Registration #8	2019-03-26	46.464 mi
Registration #9	2020-01-15	50.325 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		10.309 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1229 kg
Max. allowed weight	1601 kg
Additional information	
Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	FSX46458693