



report date: 2024-03-28

General information

Make	SUZUKI
Model	ALTO SZ4
Colour	Silver
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-04
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-10
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	25
Total items failed	2

MOT #14 2024-04-11 11:05

MOT test number 190278574690

Result ✓ Passed

Next expiry date 2025-04-10

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #13 2023-04-11 11:24

MOT test number 425866028735

Result ✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush deteriorating (5.3.4 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush deteriorating (5.3.4 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12**

2022-04-08 10:39

MOT test number

454758188387

Result

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn to 3mm (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material into flexible hose (1.1.11 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush deteriorating (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material into flexible hose (1.1.11 (c))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush deteriorating (5.3.4 (a) (i))

MOT #11

2022-04-08 10:39

MOT test number

468177220197

Result

✗ Failed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush deteriorating (5.3.4 (a) (i))
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material into flexible hose (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn to 3mm (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush deteriorating (5.3.4 (a) (i))
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material into flexible hose (1.1.11 (c))



MOT #10	2021-04-06 12:37
MOT test number	205514591451
Result	✓ Passed
MOT #9	2020-10-07 08:45
MOT test number	995005349983
Result	✓ Passed
MOT #8	2019-11-16 09:49
MOT test number	829517318675
Result	✓ Passed
MOT #7	2018-11-10 11:06
MOT test number	342740817433
Result	✓ Passed
MOT #6	2017-11-11 09:06
MOT test number	567846048820
Result	✓ Passed
MOT #5	2016-11-26 11:38
MOT test number	601937474054
Result	✓ Passed
MOT #4	2015-11-28 11:56
MOT test number	329232536759
Result	✓ Passed
MOT #3	2014-09-20 09:10
MOT test number	385763464259
Result	✓ Passed



MOT #2	2013-09-19 09:27
MOT test number	365812163236
Result	✓ Passed

MOT #1	2012-09-21 14:09
MOT test number	375315862235
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
10 April 2025

Tax status	Valid until 1 May
Days left	1
MOT expiry date	10 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-25
Last registration	2024-04-11
Complete history	See info



Registration #1	2009-09-25	12 mi
Registration #2	2012-09-21	15.563 mi
Registration #3	2013-09-19	20.241 mi
Registration #4	2014-09-20	25.931 mi
Registration #5	2015-11-28	32.044 mi
Registration #6	2016-11-26	37.126 mi
Registration #7	2017-11-11	42.011 mi
Registration #8	2018-11-10	50.300 mi
Registration #9	2019-05-29	55.377 mi
Registration #10	2019-05-29	55.377 mi
Registration #11	2019-05-29	55.377 mi
Registration #12	2019-05-29	55.377 mi
Registration #13	2019-05-29	55.377 mi
Registration #14	2019-05-29	55.377 mi
Registration #15	2019-05-29	55.377 mi
Registration #16	2019-05-29	55.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1009612