





report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA DESIGN
Colour	Silver
Year of manufacture	2009
Top speed	106 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	79 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.9 mpg
CO2 emission	142 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date 2022-02-05

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2022-02-04
Pictures	14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



FD09ZRC report date: 2024-03-29

MOT history

MOT expiry date	2025-04-11
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	19
Total items failed	1

MOT #14	2024-04-06 09:56
MOT test number	825301631649
Result	✓ Passed
Next expiry date	2025-04-11

CarCheck.co.uk page 3/12

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Splitting (5.3.4 (a) (i)) Nearside Front Tyre worn close to legal limit/worn on edge Wearing bald to inner, splits in the **Advice** tread but no cords (5.2.3 (e)) **Advice** Nearside Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c)) Nearside Front Wheel trim obstructing tyre valve Advice Advice Offside Front Tyre slightly damaged/cracking or perishing Splits to inner and slight cracking to outer (5.2.3 (d) (ii)) Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Advice Splitting and starting to de-bond (5.3.4 (a) (i)) Offside Rear Tyre slightly damaged/cracking or perishing Heavy perishing, dated 2009 (5.2.3 (d) **Advice** (ii)) **Advice** Offside Front Brake pipe corroded, covered in grease or other material To flexible hose slight corrosion (1.1.11 (c)) Offside Front Tyre worn close to legal limit/worn on edge Worn bald to inner, splits in the tread but **Advice** no cords (5.2.3 (e)) Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f)) Nearside Front Tyre slightly damaged/cracking or perishing Splits to inner and slight cracking to Advice

Advice Rear Registration plate deteriorated but not likely to be misread Cracked (0.1 (b))

Advice Nearside Front Slight play in strut top mount

outer (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Slight (5.2.3 (d) (ii))



report date: 2024-03-29

MOT #13 2023-03-17 15:33

MOT test number 830952572256

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre slightly damaged/cracking or perishing osr tyre has signs of age deterioration within the tread (5.2.3 (d) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement osf lower arm rear most mounting perishing (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement nsf lower arm rear most mounting perishing (5.3.4 (a) (i))

Advice Nearside Front Upper nsf strut top mounting has noticeably more play than the osf but not considered excessive

MOT #12 2022-04-12 12:39

MOT test number 358521972637

Result ✓ Passed

MOT #11 2021-07-09 11:38

MOT test number 766897726121

Result ✓ Passed

MOT #10 2020-07-10 13:25

MOT test number 437072217322

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #9 2019-07-08 12:22

MOT test number 615274630583

Result ✓ Passed

MOT #8 2018-07-17 11:53

MOT test number 761473092647

Result

Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #7		2017-07-14 14:49
MOT test number		603796518625
Result		✓ Passed
MOT #6		2017-07-14 14:49
MOT test number		169038059546
Result		≍ Failed
Pass with rectification	Offside Front coil spring broken (2.4.C.1a)	
MOT #5		2016-07-29 07:37
MOT test number		746515147822
Result		✓ Passed
MOT #4		2015-07-09 15:24
MOT test number		969580095124
Result		✓ Passed
MOT #3		2014-07-23 12:14
MOT test number		905424704274
Result		✓ Passed
MOT #2		2013-07-31 10:45
MOT test number		375582613420
Result		✓ Passed
MOT #1		2012-07-27 10:53
MOT #1 MOT test number		419249902275
Result		✓ Passed
Nesuit		√ Fasseu

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

FD09ZRC

report date: 2024-03-29

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

See in this check if this VAUXHALL had different number plates.

More info >

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-07-30
Last registration	2024-04-06
Complete history	See info



Registration #1	2009-07-30	8 mi
Registration #2	2012-07-27	7.257 mi
Registration #3	2013-07-31	10.123 mi
Registration #4	2014-07-23	13.773 mi
Registration #5	2015-07-09	16.758 mi
Registration #6	2016-07-29	18.785 mi
Registration #7	2017-07-14	21.152 mi
Registration #8	2017-07-14	21.152 mi
Registration #9	2018-07-17	22.555 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.177 es

More info >

CarCheck.co.uk page 11/12



FD09ZRC report date: 2024-03-29

Safety ratings

NCAP rating	***
-------------	-----

Video <u>see crash video</u>



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1040 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	1150820

CarCheck.co.uk page 12/12