



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO SE TDI (80BHP)
Colour	Grey
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	195 Nm at 2.200 rpm
Engine capacity	1.400 cc
Cylinders	3
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-06-14
Pictures	4
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-01
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	27
Total items failed	17

MOT #20	2023-06-16 07:53
MOT test number	177568922535
Result	✓ Passed
Next expiry date	2024-07-01
Minor	Brake warning device malfunctioning or defective brake pad warning light illuminated (1.1.4 (a) (i))

MOT #19	2022-06-28 09:39
MOT test number	680437626163
Result	✓ Passed

MOT #18	2022-06-24 08:57
MOT test number	602967119678
Result	✗ Failed
Fail	Service brake efficiency below requirements (1.2.2 (a) (i))
Fail	Offside Front Direction indicator incorrect colour (4.4.3 (a))
Fail	Offside Front Headlamp aim too low (4.1.2 (a))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Nearside Front Headlamp aim too low (4.1.2 (a))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #17** 2021-07-02 15:21**MOT test number** 324668975222**Result** ✓ Passed**Advice** Rear Exhaust silencer corroded**MOT #16** 2021-07-02 15:21**MOT test number** 768421561367**Result** ✗ Failed**Advice** Rear Exhaust silencer corroded**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #15** 2020-10-01 14:08**MOT test number** 645365173299**Result** ✓ Passed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Some undertrays fitted obscuring some components**MOT #14** 2020-09-23 14:30**MOT test number** 130708825635**Result** ✗ Failed**Advice** Some undertrays fitted obscuring some components**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords and worn badly on inner edge (5.2.3 (d) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Rear Lower Coil spring fractured or broken pig tail (5.3.1 (b) (i))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**MOT #13**

2019-09-16 09:37

MOT test number

332475509198

Result

✓ Passed

- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Nearside front tyre worn on outer edge
- Advice** Some imbalance in rear foot brakes offside lower effort
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Covers fitted to underside of vehicle , exhaust back box outer skin corroded

MOT #12

2018-09-18 07:48

MOT test number

603607522564

Result

✓ Passed

- Advice** Service light on , cover fitted to underside of engine bay
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Nail in nearside rear tyre (inner edge treaded area
- Advice** Exhaust outer skin corroded/split

MOT #11

2017-09-19 09:20

MOT test number

604895798866

Result

✓ Passed

- Advice** Nearside Play in steering rack inner joint(s)

MOT #10

2016-09-09 12:15

MOT test number

649297558511

Result

✓ Passed

- Advice** Covers fitted

**MOT #9**

2016-09-09 07:54

MOT test number

710615639404

Result**✗ Failed****Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Power steering pipe(s) or hose(s) leaking (2.3.3b)**Advice** Covers fitted**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8**

2015-09-09 11:09

MOT test number

842580011942

Result**✓ Passed****Advice** Both front tyres worn on inner edges**MOT #7**

2015-09-09 11:09

MOT test number

133624067628

Result**✗ Failed****Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Both front tyres worn on inner edges**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #6**

2014-09-19 15:44

MOT test number

465582264228

Result**✓ Passed****Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2013-09-24 14:00**MOT test number** 386377263445**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2012-09-27 15:52**MOT test number** 937521172292**Result** ✓ Passed**MOT #3** 2012-03-30 09:23**MOT test number** 898000292075**Result** ✓ Passed**MOT #2** 2011-04-09 09:50**MOT test number** 126239191077**Result** ✓ Passed**MOT #1** 2011-04-09 09:50**MOT test number** 535059591048**Result** ✗ Failed**Pass with rectification** Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
1 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	1 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<div><div></div><div>XXXXXX</div></div>
Plate since	2019-06-29
Current registration	<div><div></div><div>XXXXXX</div></div>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-04-29
Last registration	2023-06-16
Complete history	See info



Registration #1	2008-04-29	22 mi
Registration #2	2011-04-09	20.787 mi
Registration #3	2012-03-30	27.278 mi
Registration #4	2012-09-27	30.096 mi
Registration #5	2013-09-24	37.049 mi
Registration #6	2014-09-19	43.631 mi
Registration #7	2015-09-09	50.134 mi
Registration #8	2015-09-09	50.134 mi
Registration #9	2016-09-09	56.551 mi
Registration #10	2016-09-09	56.551 mi
Registration #11	2017-09-19	61.670 mi
Registration #12	2018-09-19	66.789 mi
Registration #13	2019-09-19	71.908 mi
Registration #14	2020-09-19	77.027 mi
Registration #15	2021-09-19	82.146 mi
Registration #16	2022-09-19	87.265 mi
Registration #17	2023-06-16	92.384 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

BNV115675