



report date: 2024-03-29

General information

Make	CITROEN
Model	NEMO 660 LX STOP AND START HDI
Colour	White
Year of manufacture	2010
Top speed	97 mph
0 - 60 mph	16.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	60.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-03-17
Pictures	11
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-11-07
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	43
Total items failed	14

MOT #15 2023-11-01 08:44

MOT test number 482666712396

Result ✓ Passed

Next expiry date 2024-11-07

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #14 2022-11-08 09:44

MOT test number 709977646812

Result ✓ Passed

MOT #13 2021-11-01 16:02

MOT test number 870684228711

Result ✓ Passed

- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))

**MOT #12**

2021-10-01 15:58

**MOT test number**

491481830642

**Result****✗ Failed**

- Fail** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Suspension component attachment bracket/mounting likely to fail both front upper (5.3.3 (b) (ii))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Engine noisy
- Advice** Oil leak, but not excessive top of engine area (8.4.1 (a) (i))
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
- Advice** Coil spring corroded both rear (5.3.1 (b) (i))
- Fail** Offside Rear Shock absorbers has an excessively worn bush upper bush (5.3.2 (c))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Rear tyre badly age cracking
- Fail** Offside Front Headlamp aim not tested (4.1.2 (b))
- Fail** Fuel tank leaking (6.1.3 (b) (i))
- Advice** Coolant leak metal coolant pipe corroded
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Shock absorbers has an excessively worn bush upper bush (5.3.2 (c))

**MOT #11**

2020-10-01 15:55

**MOT test number**

586481507211

**Result**

✓ Passed

- Advice** Engine noisy
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users blue (8.2.2.2 (c))
- Advice** Power steering close to minimum mark (2.1.5 (b) (i))
- Advice** Coil spring corroded both rear (5.3.1 (b) (i))
- Advice** Nearside Rear tyre age cracking
- Advice** Tyre worn close to legal limit/worn on edge both front tyres badly worn on inside edge (5.2.3 (e))

**MOT #10**

2020-10-01 13:31

**MOT test number**

711973716905

**Result**

✗ Failed

- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users blue (8.2.2.2 (c))
- Fail** Nearside Front Power steering pipe/hose leaking metal pipe (2.1.5 (a))
- Advice** Nearside Rear tyre age cracking
- Advice** Tyre worn close to legal limit/worn on edge both front tyres badly worn on inside edge (5.2.3 (e))
- Advice** Power steering close to minimum mark (2.1.5 (b) (i))
- Advice** Coil spring corroded both rear (5.3.1 (b) (i))
- Advice** Engine noisy

**MOT #9**

2019-09-26 07:04

**MOT test number**

994861041022

**Result**

✓ Passed



<b>MOT #8</b>	2018-11-27 14:33
<b>MOT test number</b>	541535671704
<b>Result</b>	✓ Passed
<b>Minor</b>	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

<b>MOT #7</b>	2018-11-27 09:43
<b>MOT test number</b>	371728550369
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge NEEDS CHANGING (5.2.3 (e))
<b>Advice</b>	Engine oil light flashing
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge NEEDS CHANGING (5.2.3 (e))
<b>Minor</b>	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
<b>Fail</b>	Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))

<b>MOT #6</b>	2017-12-16 12:30
<b>MOT test number</b>	604356907138
<b>Result</b>	✓ Passed
<b>Advice</b>	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #5** 2016-12-14 11:14**MOT test number** 630764803490**Result** ✓ Passed

- Advice** Nearside Front coil spring corroded Lower section (2.4.C.1b)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Both (2.4.G.2)
- Advice** Offside Front coil spring corroded Lower section (2.4.C.1b)
- Advice** Rear Both tyre's cracking from age
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #4** 2015-12-01 09:57**MOT test number** 418169081109**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #3** 2014-12-10 11:24**MOT test number** 957124544388**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



MOT #2	2014-12-09 15:12
MOT test number	527563044356
Result	✗ Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Engine covers fitted obscuring some components in the engine bay
Fail	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1	2013-11-21 11:17
MOT test number	187105123378
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
7 November 2024

Tax status		Valid until 1 May
Days left		366
MOT expiry date		7 November 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-12-18
Last registration	2023-11-01
Complete history	<a href="#">See info</a>



Registration #1	2010-12-18	21 mi
Registration #2	2013-11-21	24.143 mi
Registration #3	2014-12-09	36.087 mi
Registration #4	2014-12-10	36.095 mi
Registration #5	2015-12-01	60.862 mi
Registration #6	2016-12-14	76.447 mi
Registration #7	2017-12-16	95.826 mi
Registration #8	2018-11-27	117.746 mi
Registration #9	2018-11-27	117.750 mi
Registration #10	2019-11-27	117.750 mi
Registration #11	2019-11-27	117.750 mi
Registration #12	2019-11-27	117.750 mi
Registration #13	2019-11-27	117.750 mi
Registration #14	2019-11-27	117.750 mi
Registration #15	2019-11-27	117.750 mi
Registration #16	2019-11-27	117.750 mi
Registration #17	2019-11-27	117.750 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	74%
Pedestrian	55%
Safety systems	29%
Overall rating	58%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1684 mm
Height	1721 mm
Length	3864 mm
Kerb weight	1090 kg
Max. allowed weight	1750 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	00013854417