



report date: 2024-03-28

General information

Make	MAZDA
Model	3 SPORT
Colour	Grey
Year of manufacture	2009
Top speed	128 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	151 BHP
Max. torque	191 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	52.3 mpg
Consumption combined	41.5 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-01
Pictures	2
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT expiry date	2025-03-30
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	18
Total items failed	0

MOT #14	2024-03-27 11:28
MOT test number	991258388128
Result	✓ Passed
Next expiry date	2025-03-30

MOT #13	2023-03-31 10:20
MOT test number	592717628906
Result	✓ Passed

MOT #12	2022-02-25 13:45
MOT test number	307826443524
Result	✓ Passed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing starting to crack/perish on inner sidewall and outer edge 205-50-17 (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner and outer edges (5.2.3 (e))

MOT #11	2021-02-27 12:26
MOT test number	800739152234
Result	✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**MOT #10** 2020-07-08 14:36**MOT test number** 707785454801**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #9** 2020-07-08 13:42**MOT test number** 408580123089**Result** ✗ Failed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**DANGEROUS** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #8** 2019-07-17 14:00**MOT test number** 234714495450**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear rubber bushes deteriorated , both sides (5.3.4 (a) (i))**Advice** Items removed from driver's view prior to test**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #7** 2018-07-13 13:53**MOT test number** 325401970533**Result** ✓ Passed

**MOT #6** 2017-07-17 12:48**MOT test number** 347161456371**Result** ✓ Passed**Advice** Covers & shields fitted not allowing full inspection**MOT #5** 2016-07-13 11:57**MOT test number** 481168086330**Result** ✓ Passed**MOT #4** 2015-07-20 14:52**MOT test number** 375061505284**Result** ✓ Passed**Notice** Cut in nearside front tyre outer wall , no cords showing**Advice** Offside Rear reflector slightly damaged but function not impaired (1.5.1c)**Notice** Items removed from driver's view prior to test**MOT #3** 2014-07-11 14:03**MOT test number** 259002594433**Result** ✓ Passed**MOT #2** 2013-07-19 14:41**MOT test number** 828950303280**Result** ✓ Passed**MOT #1** 2012-07-12 11:44**MOT test number** 208804092454**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
30 March 2025

Tax status	Valid until 1 June
Days left	32
MOT expiry date	30 March 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>HN09MKJ</b>
Plate since	2019-09-28
Current registration	<b>HN09MKJ</b>
Plate since	2019-09-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-06-26
Last registration	2024-03-27
Complete history	<a href="#">See info</a>



Registration #1	2009-06-26	26 mi
Registration #2	2012-07-12	9.703 mi
Registration #3	2013-07-19	15.494 mi
Registration #4	2014-07-11	23.512 mi
Registration #5	2015-07-20	27.631 mi
Registration #6	2016-07-13	30.426 mi
Registration #7	2017-07-17	33.438 mi
Registration #8	2018-07-13	35.948 mi
Registration #9	2019-06-26	38.377 mi
Registration #10	2020-06-26	40.807 mi
Registration #11	2021-06-26	43.237 mi
Registration #12	2022-06-26	45.667 mi
Registration #13	2023-06-26	48.097 mi
Registration #14	2024-03-27	50.527 mi
Registration #15	2024-03-27	50.527 mi
Registration #16	2024-03-27	50.527 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2002 mm
Height	1470 mm
Length	4490 mm
Wheel base	2640 mm
Kerb weight	1322 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 20274249