





report date: 2024-03-29

# General information

Make	CITROEN
Model	DS3 DSTYLE
Colour	Black
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/12



# Internet history

## Entry 6

Date 2023-05-08

Pictures 0

Listing price <u>View report</u>

#### source: carcraft.co.uk

## Entry 5

Date 2021-10-20

Pictures 2

Listing price <u>View report</u>





# source: autotrader.co.uk

## Entry 4

Date	2021-10-01
D' I	

Pictures 1

Listing price <u>View report</u>



## source: cargurus.co.uk


#### Entry 3


Date	2021-08-30
Pictures	4
Listing price	View report

CarCheck.co.uk page 2/12









source: autotrader.co.uk

Entry 2

Date 2023	07-25
-----------	-------

Pictures 19

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2021-07-23
-----------------

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-23
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	10
Total items failed	9

MOT #12		2023-07-24 15:30
MOT test	number	123594784443
Result		✓ Passed
Next expi	ry date	2024-07-23
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #11	2023-07-24 15:30
MOT test number	983813108124
Result	<b>X</b> Failed
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))
Pass with rectification	Nearside Front Headlamp aim projected beam image is obviously incorrect
(4.1.2 (c))	
Advice Offside Front Tyr	re slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Pass with rectification	Offside Rear Seat belt buckle missing (7.1.2 (d))
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))
Pass with rectification	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2
(c))	
Advice Nearside Rear Ty	yre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 3/12



MT14DTK

report date: 2024-03-29

MOT #10	2022-10-13 13:59

**MOT test number** 801356658927

MOT #9 2022-01-13 13:33

**MOT test number** 194616242247

**Result** ✓ Passed

MOT #8 2021-07-01 14:31

**MOT test number** 453722171501

**Result** ✓ Passed

MOT #7 2020-08-21 09:01

**MOT test number** 882912442970

**Result** ✓ Passed

MOT #6 2020-08-21 09:01

**MOT test number** 628569091220

Result X Failed

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #5 2019-08-19 15:39

**MOT test number** 332615510428

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

CarCheck.co.uk page 4/12



MT14DTK

report date: 2024-03-29

MOT test number

Result

Advice
Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice
Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice
Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification
Offside Front Headlamp aim too low (4.1.2 (a))

MOT #3	2018-09-01 12:36
MOT test number	242358926072
Result	<b>✓</b> Passed
MOT #2	2018-09-01 08:38
MOT test number	315576130111
Result	<b>X</b> Failed
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Windscreen washer not working (3.5 (a))	

MOT #1	2017-08-31 14:15
MOT test number	136419306825
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	23 July 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



MT14DTK

report date: 2024-03-29

# Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



## Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
	More info >
Plate changes  See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info

CarCheck.co.uk page 9/12



# Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2014-05-24
Last registration	2023-07-24
Complete history	See info



Registration #1	2014-05-24	14 mi
Registration #2	2017-08-31	13.912 mi
Registration #3	2018-09-01	20.500 mi
Registration #4	2018-09-01	20.500 mi
Registration #5	2019-08-19	24.037 mi
Registration #6	2019-08-19	24.037 mi
Registration #7	2020-08-21	30.177 mi
Registration #8	2020-08-21	30.177 mi
Registration #9	2021-07-01	34.919 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11,177 ms

More info >

CarCheck.co.uk page 11/12



# Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



# Dimensions & weight

Width	1708 mm
Height	1460 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1075 kg
Max. allowed weight	1554 kg

# Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FHCA2082498

CarCheck.co.uk page 12/12