





report date: 2024-03-28

General information

Make	MERCEDES
Model	ML ML270 CDI SPECIAL EDITION
Colour	Silver
Year of manufacture	2004
Top speed	114 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	370 Nm at 1.800 rpm
Engine capacity	2.685 cc
Cylinders	5
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	37.2 mpg
Consumption combined	31.0 mpg
CO2 emission	241 g/km
CO2 label	L



CarCheck.co.uk page 1/14



AP54EJD

report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-09

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2025-04-02
MOT pass rate	86 %
MOT passed	18
Failed MOT tests	3
Total advice items	30
Total items failed	6

MOT #21		2024-04-03 09:35
MOT test	number	387803888838
Result		✓ Passed
Next expi	ry date	2025-04-02
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #20	2024-03-26 16:07
MOT test number	312334547545
Result	× Failed
Fail Offside Parking brake inoperative on one side (1.4.1 (a))	
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	

CarCheck.co.uk page 3/14



MOT #19 2023-03-27 12:01

MOT test number 157582131755

Result \rightarrow Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Handbrake effort lower in comparison to nearside

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #18 2022-03-23 12:48

MOT test number 423807382962

Result ✓ Passed

MOT #17 2021-09-08 09:57

MOT test number 396474051308

Result ✓ Passed

MOT #16 2020-11-19 18:26

MOT test number 995718584730

Result

Passed

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/14



MOT #15 2019-01-14 14:17

MOT test number 132146555303

Result ✓ Passed

Advice Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4

(b))

Advice Offside Rear tre wearing on inner edge

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2018-01-25 12:15

MOT test number 533495338465

Result ✓ Passed

MOT #13 2017-01-12 10:24

MOT test number 399694958291

Result ✓ Passed

MOT #12 2016-01-14 11:33

MOT test number 536350442316

Result ✓ Passed

MOT #11 2015-01-27 10:52

MOT test number 208007625060

Result \(\sqrt{Passed} \)

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 5/14



MOT #10

MOT test number

957502924063

Result

Advice Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

Advice Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #9 2013-01-21 10:09 **MOT** test number 837031623061 Result ✓ Passed MOT #8 2012-01-25 10:39 146365722475 **MOT test number** Result Passed MOT #7 2011-01-20 11:14 **MOT test number** 257450021051 Result ✓ Passed MOT #6 2010-01-20 10:52 **MOT** test number 801390120008 Result ✓ Passed **Notice** Both rear tyres wearing low

MOT #5	2009-01-16 13:40
MOT test number	401516219054
Result	✓ Passed

CarCheck.co.uk page 6/14



Advice

AP54EJD report date: 2024-03-28

MOT #4 2009-01-15 16:07
MOT test number 850745919073

Result × Failed

Fail Registration plate character(s) incorrectly spaced (6.3.4a)

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3

MOT test number

861169228023

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Advice Offside Rear Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Advice Nearside Rear Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT test number

122710437328

Result

Kesult

Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

Advice

Nearside Rear Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Fail

Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

Advice

Offside Rear Lower Suspension arm has slight play in a ball joint (2.4.G.2)

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	2 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category
Type

Damage 2

Date Category

Туре



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner	history
OWITEL	HISLULY

o mile mistery	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NIE AIS UK
Plate since	
Current registration	OK SIES
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-11-26
Last registration	2024-04-03
Complete history	See info



Registration #1	2004-11-26	23 mi
Registration #2	2007-11-26	20.741 mi
Registration #3	2007-11-26	20.741 mi
Registration #4	2008-01-29	21.361 mi
Registration #5	2009-01-15	25.298 mi
Registration #6	2009-01-16	25.301 mi
Registration #7	2010-01-20	27.728 mi
Registration #8	2011-01-20	30.229 mi
Registration #9	2012-01-25	31.620 mi
Registration #10	2013-01-21	34.252 mi
Registration #11	2014-01-22	40.498 mi
Registration #12	2015-01-27	49.432 mi
Registration #13		11.177 es
Registration #14		11.117 es
Registration #15		11.177 es
Registration #16		11.117 es
Registration #17		11.177 mi
Registration #18		11.117 es
Registration #19		11.177 mi
Registration #20		11.117 es
Registration #21		11.777 es
Registration #22		0.00 44
Registration #23		10.777 au

More info >

CarCheck.co.uk page 13/14



Dimensions & weight

Width	2126 mm
Height	1820 mm
Length	4638 mm
Wheel base	2820 mm
Max. allowed weight	2870 kg

Additional information

Fuel tank capacity	83 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	61296330332915

CarCheck.co.uk page 14/14