



BT60XWK

report date: 2024-03-28

General information

Make	MAZDA
Model	3 D TS2
Colour	Grey
Year of manufacture	2011
Top speed	114 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-12
Pictures	13
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-08
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	29
Total items failed	11

MOT #17	2023-06-07 07:59
MOT test number	128694737281
Result	✓ Passed
Next expiry date	2024-06-08
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2022-06-04 10:33
MOT test number	894040618080
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15**

2022-06-03 10:04

MOT test number

794664030793

Result**✗ Failed****Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #14**

2021-06-09 11:27

MOT test number

809496764302

Result**✓ Passed****Advice** Front Suspension arm corroded but not seriously weakened both front (5.3.3 (b) (i))**Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Suspension arm corroded but not seriously weakened both rear (5.3.3 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13**

2021-06-09 11:27

MOT test number

270987542992

Result**✗ Failed****Advice** Rear Suspension arm corroded but not seriously weakened both rear (5.3.3 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Suspension arm corroded but not seriously weakened both front (5.3.3 (b) (i))**Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #12** 2020-05-05 10:46**MOT test number** 881194027462**Result** ✓ Passed**MOT #11** 2020-05-05 08:10**MOT test number** 335260916508**Result** ✗ Failed**Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** O/s front window inoperative**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10** 2019-05-09 09:37**MOT test number** 829954580831**Result** ✓ Passed**MOT #9** 2019-05-08 09:21**MOT test number** 748988493527**Result** ✗ Failed**Fail** Reversing lamp inoperative (4.6.1 (a))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Fail** Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))

**MOT #8** 2018-05-08 10:10**MOT test number** 574846606556**Result** ✓ Passed**Advice** Front tyres wearing on the edges of the tread.**MOT #7** 2018-05-08 06:26**MOT test number** 397661427250**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front tyres wearing on the edges of the tread.**MOT #6** 2017-05-08 12:30**MOT test number** 104742879509**Result** ✓ Passed**MOT #5** 2017-05-08 07:56**MOT test number** 400556776499**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2016-04-25 08:08**MOT test number** 565588540093**Result** ✓ Passed**Advice** Front tyres heavily worn on the inner edges of the tread, replacement recommended.

**MOT #3** 2015-04-24 08:18**MOT test number** 928414315111**Result** ✓ Passed

- Advice** Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

MOT #2 2014-05-12 14:39**MOT test number** 985902434118**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components

MOT #1 2013-10-25 10:05**MOT test number** 529448493297**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Age related cracks to both front tyres



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
8 June 2024

Tax status	Valid until 1 May
Days left	1
MOT expiry date	8 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	BT60XWK
Plate since	2019-09-28
Current registration	BT60XWK
Plate since	2019-09-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-01-10
Last registration	2023-06-07
Complete history	See info



Registration #1	2011-01-10	13 mi
Registration #2	2013-10-25	45.972 mi
Registration #3	2014-05-12	50.414 mi
Registration #4	2015-04-24	59.348 mi
Registration #5	2016-04-25	68.859 mi
Registration #6	2017-05-08	79.699 mi
Registration #7	2017-05-08	79.699 mi
Registration #8	2018-05-08	89.141 mi
Registration #9	2018-05-08	89.141 mi
Registration #10	2019-05-08	100.848 mi
Registration #11	2019-05-08	100.848 mi
Registration #12	2019-05-08	100.848 mi
Registration #13	2019-05-08	100.848 mi
Registration #14	2019-05-08	100.848 mi
Registration #15	2019-05-08	100.848 mi
Registration #16	2019-05-08	100.848 mi
Registration #17	2019-05-08	100.848 mi
Registration #18	2019-05-08	100.848 mi
Registration #19	2019-05-08	100.848 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2002 mm
Height	1470 mm
Length	4480 mm
Wheel base	2640 mm
Kerb weight	1323 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	Y6 318577