



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT TDI SPORT 5 STR
Colour	Grey
Year of manufacture	2009
Top speed	122 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-07
Pictures	3
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-11-23
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	19
Total items failed	2

MOT #15	2023-11-24 09:38
MOT test number	330356559403
Result	✓ Passed
Next expiry date	2024-11-23

MOT #14	2022-10-07 08:09
MOT test number	305796405636
Result	✓ Passed
Advice	Tyre worn close to legal limit/worn on edge all 4 tyres (5.2.3 (e))
Advice	Tyre slightly damaged/cracking or perishing ALL 4 TYRES PERISHED WORN ON INNER EDGE (5.2.3 (d) (ii))

MOT #13	2021-10-08 14:05
MOT test number	863270508216
Result	✓ Passed

MOT #12	2020-10-12 07:47
MOT test number	137667661063
Result	✓ Passed
Advice	Central Rear Seat belt buckle slightly damaged (7.1.2 (d))
Advice	No smoke readings available as software prevents

**MOT #11** 2019-06-18 09:34**MOT test number** 304465101503**Result** ✓ Passed**Advice** O EMISSIONS**MOT #10** 2018-06-14 11:30**MOT test number** 709877709541**Result** ✓ Passed**Advice** Zero emissions test result**MOT #9** 2017-06-13 09:56**MOT test number** 970405378166**Result** ✓ Passed**Advice** Zero emissions test result**MOT #8** 2017-06-13 07:32**MOT test number** 454625827430**Result** ✗ Failed**Advice** Zero emissions test result**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #7** 2016-06-14 07:12**MOT test number** 695024461597**Result** ✓ Passed**Advice** Zero emissions test result**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front tyre worn low at edges

**MOT #6** 2015-06-02 09:43**MOT test number** 259423355161**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-06-10 09:36**MOT test number** 995831664160**Result** ✓ Passed**Notice** Both rear tyres starting to crack around outer edges**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-06-11 11:58**MOT test number** 107362163155**Result** ✓ Passed**Notice** Zero emissions, too low to start analyzer**Notice** O/s/f and o/s/r tyres starting to crack and perish around outer edges**MOT #3** 2012-06-21 10:37**MOT test number** 976783072180**Result** ✓ Passed**Notice** Engine emissions too low to start analyzer**MOT #2** 2012-04-16 11:35**MOT test number** 607877302132**Result** ✓ Passed**Advice** Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #1	2012-04-16 11:35
MOT test number	647007002178
Result	✗ Failed
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
23 November 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	23 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>ND09HXZ</b>
Plate since	2024-03-29
Current registration	 <b>ND09HXZ</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-05-15
Last registration	2023-11-24
Complete history	<a href="#">See info</a>



Registration #1	2009-05-15	9 mi
Registration #2	2012-04-16	11.137 mi
Registration #3	2012-06-21	11.592 mi
Registration #4	2013-06-11	11.635 mi
Registration #5	2014-06-10	21.772 mi
Registration #6	2015-06-02	26.524 mi
Registration #7	2016-06-14	29.154 mi
Registration #8	2017-06-13	30.565 mi
Registration #9	2018-06-13	31.277 mi
Registration #10	2019-06-13	31.277 mi
Registration #11	2020-06-13	31.277 mi
Registration #12	2021-06-13	31.277 mi
Registration #13	2022-06-13	31.277 mi
Registration #14	2023-06-13	31.277 mi
Registration #15	2023-11-24	31.277 mi
Registration #16	2023-11-24	31.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1561 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKD C72007