



report date: 2024-03-29

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Red
Year of manufacture	-
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg






LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-12
Pictures	9
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #18	2022-12-06 11:42
MOT test number	440643008054
Result	✓ Passed
Next expiry date	2023-12-05
Advice	Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))
Advice	Rear Coil spring corroded Both (5.3.1 (b) (i))

MOT #17	2022-12-03 13:00
MOT test number	763518911971
Result	✗ Failed
Fail	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Advice	Rear Coil spring corroded Both (5.3.1 (b) (i))
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Central Front Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))
Fail	Emissions not tested (8.2.1.2 (d))

MOT #16	2021-09-23 13:18
MOT test number	995576333729
Result	✓ Passed
Advice	Front Coil spring corroded and rear (5.3.1 (b) (i))

**MOT #15**

2020-10-07 13:14

MOT test number

905859794882

Result

✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #14

2020-09-30 09:56

MOT test number

268381139047

Result

✗ Failed

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Rear Brake pipe excessively corroded From hose to wheel cylinder (1.1.11 (c))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Rear Brake pipe excessively corroded From hose to wheel cylinder (1.1.11 (c))
- Fail** Horn not working (7.7 (a) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #13**

2019-09-30 14:02

MOT test number

499713073887

Result

✓ Passed

- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material Corroded (1.1.11 (c))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Horn not working properly (7.7 (a) (i))

MOT #12

2018-10-01 16:04

MOT test number

329770448134

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Nail in tread (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Nail in tread (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2018-10-01 11:23

MOT test number

283239465587

Result**✗ Failed**

- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Nail in tread (5.2.3 (e))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Nail in tread (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Brake pipe excessively corroded Front to rear (1.1.11 (c))

MOT #10

2017-06-02 09:55

MOT test number

239824125631

Result**✓ Passed**

- Advice** Nearside Brake pipe slightly corroded Front to rear at rear (3.6.B.2c)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Tyre worn close to the legal limit Inside edge (4.1.E.1)

**MOT #9** 2017-05-30 14:03**MOT test number** 306368570156**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Brake pipe slightly corroded Front to rear at rear (3.6.B.2c)**Fail** Offside Brake pipe excessively corroded Front to rear (3.6.B.2c)**Advice** Offside Front Tyre worn close to the legal limit Inside edge (4.1.E.1)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #8** 2016-05-28 10:58**MOT test number** 716196328528**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement back bush (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement back bush (2.4.G.2)**MOT #7** 2015-05-22 15:13**MOT test number** 248882145110**Result** ✓ Passed**Notice** O/s wiper smears slightly**MOT #6** 2015-05-22 10:52**MOT test number** 516992545105**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** O/s wiper smears slightly

**MOT #5** 2014-05-23 16:11**MOT test number** 435753244148**Result** ✓ Passed**Notice** N/s/f wiper blade poor**Advice** Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #4** 2014-05-21 15:51**MOT test number** 878461744162**Result** ✗ Failed**Advice** Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**Notice** N/s/f wiper blade poor**Fail** Nearside Front front brake binding (3.7.B.1)**MOT #3** 2013-05-21 16:36**MOT test number** 289771643186**Result** ✓ Passed**Notice** O/s+n/s front susp arms rear bush starting to split**MOT #2** 2012-08-29 11:30**MOT test number** 109372042295**Result** ✓ Passed**MOT #1** 2012-08-29 11:30**MOT test number** 217472142226**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-12
Last registration	2022-12-06
Complete history	See info



Registration #1	2009-09-12	22 mi
Registration #2	2012-08-29	26.573 mi
Registration #3	2013-05-21	35.514 mi
Registration #4	2014-05-21	43.518 mi
Registration #5	2014-05-23	43.557 mi
Registration #6	2015-05-22	50.145 mi
Registration #7	2015-05-22	50.145 mi
Registration #8	2016-05-28	56.257 mi
Registration #9	2017-05-30	63.395 mi
Registration #10	2017-06-02	63.457 mi
Registration #11	2018-05-29	69.377 mi
Registration #12	2019-05-29	75.377 mi
Registration #13	2020-05-29	81.377 mi
Registration #14	2021-05-29	87.377 mi
Registration #15	2022-05-29	93.377 mi
Registration #16	2023-05-29	99.377 mi
Registration #17	2024-05-29	105.377 mi
Registration #18	2025-05-29	111.377 mi
Registration #19	2026-05-29	117.377 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	107462