



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	A-CLASS A150 CLASSIC SE
Colour	Black
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	140 Nm at 3.500 rpm
Engine capacity	1.498 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	52.3 mpg
Consumption combined	45.6 mpg
CO2 emission	148 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-05-26
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-13
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	52
Total items failed	3

MOT #15	2023-06-14 13:42
MOT test number	738140530951
Result	✓ Passed
Next expiry date	2024-06-13
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Both rear tyres cracking though out tread

**MOT #14**

2023-06-07 13:57

MOT test number

506367556832

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Horn not working (7.7 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Front Shock absorbers has negligible damping effect (5.3.2 (d))
- MAJOR** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- MAJOR** Windscreen washer not working (3.5 (a))
- Advice** Both rear tyres cracking though out tread
- MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #13

2022-04-14 14:47

MOT test number

585752027243

Result**✓ Passed**

- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front steering arm has play in joint
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Both rear tyres cracking though out tread

**MOT #12**

2022-04-09 09:54

MOT test number

329148386545

Result**✗ Failed****MAJOR** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Offside Front steering arm has play in joint**MAJOR** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Both rear tyres cracking though out tread**MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #11**

2021-04-02 13:53

MOT test number

475199101504

Result**✓ Passed****Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Both rear tyres cracking through out tread**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Brake pipe corroded, covered in grease or other material both front to rear pipes (1.1.11 (c))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2019-07-05 13:02

MOT test number

515478203111

Result

✓ Passed

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9

2018-05-03 12:50

MOT test number

348168636092

Result

✓ Passed

MOT #8

2017-05-09 09:19

MOT test number

518593242621

Result

✓ Passed

- Advice** Nearside Rear Tyre has slight cracking inside treads

MOT #7

2017-05-09 09:19

MOT test number

283999781406

Result

✗ Failed

- Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Nearside Rear Tyre has slight cracking inside treads
- Pass with rectification** Offside Headlamp aim too high (1.8)
- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)

**MOT #6** 2016-11-11 11:48**MOT test number** 245244336674**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit approx.3mm (4.1.E.1)**Advice** Both front tyres worn on outer edges**Advice** Both front suspension arm bushes(front of) slightly worn**MOT #5** 2015-11-12 09:46**MOT test number** 164541087219**Result** ✓ Passed**MOT #4** 2015-04-17 13:00**MOT test number** 219337905108**Result** ✓ Passed**Notice** Drivers wiper arm striking A pillar.**Notice** Slight corrosion on metal brake pipes.**Notice** Rear wiper torn.**Notice** N/S/F CV Boot twisted.**MOT #3** 2014-04-30 11:35**MOT test number** 557400524178**Result** ✓ Passed



MOT #2 2013-05-08 09:40

MOT test number 905518323172

Result ✓ Passed

- Notice** Rear brakes adjustment hand brake
- Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Notice** Twist in n/side front outer cv boot
- Notice** Rear brake discs worn
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #1 2012-05-14 16:01

MOT test number 205985032400

Result ✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
13 June 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	13 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	LM58UJK
Plate since	2019-03-29
Current registration	LM58UJK
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-11-24
Last registration	2023-06-14
Complete history	See info



Registration #1	2008-11-24	22 mi
Registration #2	2012-05-14	33.404 mi
Registration #3	2013-05-08	36.773 mi
Registration #4	2014-04-30	42.164 mi
Registration #5	2015-04-17	46.930 mi
Registration #6	2015-11-12	48.655 mi
Registration #7	2016-11-11	53.391 mi
Registration #8	2017-05-09	54.204 mi
Registration #9	2017-05-09	54.204 mi
Registration #10	2018-05-09	55.204 mi
Registration #11	2019-05-09	56.204 mi
Registration #12	2020-05-09	57.204 mi
Registration #13	2021-05-09	58.204 mi
Registration #14	2022-05-09	59.204 mi
Registration #15	2023-05-09	60.204 mi
Registration #16	2024-05-09	61.204 mi
Registration #17	2025-05-09	62.204 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1975 mm
Height	1593 mm
Length	3838 mm
Wheel base	2568 mm
Kerb weight	1225 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	26692030528223