



Mercedes-Benz

 **MT65KLU**


report date: 2024-03-29

General information

| | |
|---------------------|-----------------------------|
| Make | MERCEDES-BENZ |
| Model | CLS CLS220 BLUETEC AMG LINE |
| Colour | Silver |
| Year of manufacture | 2015 |
| Top speed | 138 mph |
| 0 - 60 mph | 8.5 seconds |
| Gearbox | 7 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 174 BHP |
| Max. torque | 400 Nm at 1.400 rpm |
| Engine capacity | 2.143 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 47.1 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 128 g/km |
| CO2 label | D |





Internet history

Entry 3




| | |
|---------------|-----------------------------|
| Date | 2023-07-15 |
| Pictures | 9 |
| Listing price | View report |



source: cargurus.co.uk

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2023-06-05 |
| Pictures | 15 |
| Listing price | View report |



source: autotrader.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-04 |
| Pictures | 18 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-03-04 |
| MOT pass rate | 64 % |
| MOT passed | 7 |
| Failed MOT tests | 4 |
| Total advice items | 14 |
| Total items failed | 6 |

| | |
|------------------|------------------|
| MOT #11 | 2024-03-05 15:50 |
| MOT test number | 931240774298 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-04 |

| | |
|-----------------|------------------|
| MOT #10 | 2023-06-10 11:04 |
| MOT test number | 126520587505 |
| Result | ✓ Passed |

| | |
|-----------------|--|
| MOT #9 | 2023-06-10 09:11 |
| MOT test number | 948444849804 |
| Result | ✗ Failed |
| Fail | Offside Rear Inner Tyre has a bulge, caused by separation or partial failure of its structure side wall (5.2.3 (d) (ii)) |

| | |
|-----------------|------------------|
| MOT #8 | 2022-06-01 09:08 |
| MOT test number | 758182167399 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #7 | 2021-06-26 09:49 |
| MOT test number | 353639211894 |
| Result | ✓ Passed |



MOT #6 2021-06-22 12:10

MOT test number 741918790145

Result ✗ Failed

- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2020-10-09 13:20

MOT test number 498852479176

Result ✓ Passed

MOT #4 2019-10-09 11:51

MOT test number 301695145677

Result ✓ Passed

- Advice** Under trays fitted not allowing full inspection.
- Advice** Front Brake pad(s) wearing thin Change disks with pads. (1.1.13 (a) (ii))

MOT #3 2019-10-09 11:51

MOT test number 103385100399

Result ✗ Failed

- Advice** Front Brake pad(s) wearing thin Change disks with pads. (1.1.13 (a) (ii))
- Pass with rectification** Offside Rear Passenger's seat backrest cannot be secured in the upright position. (6.2.6 (a) (i))
- Advice** Under trays fitted not allowing full inspection.



MOT #2 2018-10-02 10:22

MOT test number 405124435983

Result ✔ Passed

- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Camber bush. (5.3.4 (a) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2018-10-02 10:22

MOT test number 630817926514

Result ✘ Failed

- Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Camber bush. (5.3.4 (a) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
4 March 2025

Tax status Valid until 1 March

Days left 306

MOT expiry date 4 March 2025

Full MOT history [See MOT history](#)

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |




Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.


Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|------------------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | | |
|-------|-------|-----|
| Owner | Start | End |

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | MT65KLU |
| Plate since | 2019-03-29 |
| Current registration | MT65KLU |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

| | |
|--------------------------|----------|
| Finance company | REDACTED |
| Date of agreement | REDACTED |
| Agreement type | REDACTED |
| Agreement term | REDACTED |
| Agreement number | REDACTED |
| Contact info | REDACTED |

More info >



Mileage check

| | |
|-----------------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2015-10-31 |
| Last registration | 2024-03-05 |
| Complete history | See info |



| | | |
|-------------------------|------------|-----------|
| Registration #1 | 2015-10-31 | 10 mi |
| Registration #2 | 2018-10-02 | 21.097 mi |
| Registration #3 | 2018-10-02 | 21.097 mi |
| Registration #4 | 2019-10-09 | 29.576 mi |
| Registration #5 | 2019-10-09 | 29.576 mi |
| Registration #6 | 2020-10-09 | 36.571 mi |
| Registration #7 | 2020-10-09 | 36.571 mi |
| Registration #8 | 2021-06-22 | 40.706 mi |
| Registration #9 | 2021-06-22 | 40.706 mi |
| Registration #10 | 2021-06-22 | 40.706 mi |
| Registration #11 | 2021-06-22 | 40.706 mi |
| Registration #12 | 2021-06-22 | 40.706 mi |
| Registration #13 | 2021-06-22 | 40.706 mi |
| Registration #14 | 2021-06-22 | 40.706 mi |
| Registration #15 | 2024-03-05 | 40.706 mi |

[More info >](#)



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 93% |
| Children | 81% |
| Pedestrian | 67% |
| Safety systems | 86% |
| Overall rating | 85% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1881 mm |
| Height | 1418 mm |
| Length | 4937 mm |
| Wheel base | 2874 mm |
| Kerb weight | 1790 kg |
| Max. allowed weight | 2275 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 59 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |

| | |
|------------------------|----------------|
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | 65192432757022 |