



report date: 2024-03-28

General information

Make	CITROEN
Model	C2 VT
Colour	Black
Year of manufacture	2009
Top speed	98 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	94 Nm at 3.300 rpm
Engine capacity	1.124 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E



Internet history

Entry 1

Date	2022-01-04
Pictures	13
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-01-18
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	62
Total items failed	26

MOT #20 2024-01-19 13:15

MOT test number 829544499589

Result ✓ Passed

Next expiry date 2025-01-18

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Nearside Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #19 2024-01-19 13:15

MOT test number 671798782625

Result ✗ Failed

**Advice** Nearside Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))



<b>MOT #18</b>	2023-01-14 12:17
<b>MOT test number</b>	423557700191
<b>Result</b>	✓ Passed
<b>Minor</b>	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
<b>Advice</b>	Nearside Front Coil spring corroded (5.3.1 (b) (i))

<b>MOT #17</b>	2022-01-10 12:08
<b>MOT test number</b>	288334310231
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
<b>Advice</b>	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

<b>MOT #16</b>	2021-01-12 16:47
<b>MOT test number</b>	322957437413
<b>Result</b>	✓ Passed
<b>Minor</b>	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
<b>Advice</b>	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
<b>Advice</b>	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
<b>Advice</b>	Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
<b>Minor</b>	Central Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
<b>Advice</b>	Oil leak, but not excessive oil filter housing (8.4.1 (a) (i))

**MOT #15**

2021-01-08 13:32

**MOT test number**

527329875990

**Result****✗ Failed**

- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))
- Fail** Offside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Oil leak, but not excessive oil filter housing (8.4.1 (a) (i))
- Fail** Nearside Headlamp aim not tested (4.1.2 (b))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Front Coil spring worn so that its cross sectional area is reduced and seriously weakened fouling on inner wing on lock to lock (5.3.1 (b) (i))
- Fail** Nearside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))
- Minor** Central Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))

**MOT #14** 2020-01-06 14:15**MOT test number** 439972334916**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13** 2020-01-06 14:15**MOT test number** 902251334155**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Pass with rectification** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #12** 2019-07-19 14:59**MOT test number** 399497182967**Result** ✓ Passed**MOT #11** 2018-08-07 14:41**MOT test number** 344302315838**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2018-08-07 10:24

**MOT test number**

521181349880

**Result****✗ Failed**

- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Service brake lagging in operation (1.2.1 (d))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

**MOT #9**

2017-07-28 10:27

**MOT test number**

557166480402

**Result****✓ Passed**

- Advice** Oil leak
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #8 2017-07-27 15:36

MOT test number 350861553875

Result ✗ Failed

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Oil leak

**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)

MOT #7 2016-07-16 08:32

MOT test number 112565556039

Result ✓ Passed

**Advice** Oil leak

**Advice** Offside Rear Tyre cracked

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Items removed from driver's view prior to test

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6** 2016-07-16 08:32**MOT test number** 795468798702**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Items removed from driver's view prior to test**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre cracked**Advice** Oil leak**MOT #5** 2015-07-13 12:49**MOT test number** 267014595155**Result** ✓ Passed**Notice** Nearside front tyre cracked and perrished**Notice** Offside rear tyre cracked and perrished**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside front tyre cracked and perrished**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2014-07-15 10:46**MOT test number** 979866194137**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Oil leak**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-07-02 16:18**MOT test number** 488023383191**Result** ✓ Passed**MOT #2** 2013-07-02 10:21**MOT test number** 537603583105**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #1** 2012-03-30 15:47**MOT test number** 895350392091**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 May 2024

✓  
**MOT**  
  
Expires:  
18 January 2025

Tax status	Valid until 1 May
Days left	2
MOT expiry date	18 January 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-03-30
Last registration	2024-01-19
Complete history	<a href="#">See info</a>



Registration #1	2009-03-30	25 mi
Registration #2	2012-03-30	14.307 mi
Registration #3	2013-07-02	33.197 mi
Registration #4	2013-07-02	33.197 mi
Registration #5	2014-07-15	35.702 mi
Registration #6	2015-07-13	36.928 mi
Registration #7	2016-07-16	38.195 mi
Registration #8	2016-07-16	38.195 mi
Registration #9	2017-07-27	44.079 mi
Registration #10	2017-07-28	44.085 mi
Registration #11	2018-08-07	47.992 mi
Registration #12	2019-01-20	51.277 mi
Registration #13	2019-01-20	51.277 mi
Registration #14	2019-01-20	51.277 mi
Registration #15	2019-01-20	51.277 mi
Registration #16	2019-01-20	51.277 mi
Registration #17	2019-01-20	51.277 mi
Registration #18	2019-01-20	51.277 mi
Registration #19	2019-01-20	51.277 mi
Registration #20	2019-01-20	51.277 mi
Registration #21	2019-01-20	51.277 mi
Registration #22	2019-01-20	51.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1659 mm
Height	1461 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	956 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FP7W5123324