



PEUGEOT

KP57LTT


report date: 2024-03-29

General information

Make	PEUGEOT
Model	407 HDI GT
Colour	Gold
Year of manufacture	-
Top speed	129 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.9 mpg






Internet history

Entry 1

Date	2021-12-07
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history****MOT #18**

2021-12-02 20:40

MOT test number

619369418733

Result**✗ Failed**

- Fail** Undertray insecure (8.1.1 (b) (i))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Offside Rear Upper Suspension component pin or bush slightly worn (shock absorber) (5.3.4 (a) (i))
- Fail** Nearside Front Headlamp aim not tested (4.1.2 (b))
- Advice** Rear heat shield insecure at back box
- Fail** Nearside Rear Brake hose leaking on a hydraulic braking system (1.1.12 (c) (ii))
- Fail** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Minor** Nearside Front Electrical wiring inadequately secured (4.11 (a) (i))
- Advice** Power steering pump has slight seepage (2.1.5 (a))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Rear Upper Suspension component pin or bush slightly worn (shock absorber) (5.3.4 (a) (i))
- Fail** Offside Front Headlamp aim too low (4.1.2 (a))
- Advice** Rear brake ferrules corroded but not excessive
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Minor** Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Offside Rear Brake hose leaking on a hydraulic braking system (1.1.12 (c) (ii))
- Fail** Nearside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))
- Fail** Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))

**MOT #17**

2020-11-19 14:20

MOT test number

527533887103

Result

✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #16**

2020-11-11 11:05

MOT test number

999657928606

Result

✗ Failed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #15**

2019-11-11 10:50

MOT test number

883997859952

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #14	2018-10-24 09:42
MOT test number	295422826826
Result	✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13	2017-11-06 17:26
MOT test number	301461710131
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear Direction indicators slightly discoloured (1.4.A.2f)

**MOT #12**

2017-11-06 11:39

MOT test number

514436433960

Result**✗ Failed****Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Nearside Front Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Direction indicators slightly discoloured (1.4.A.2f)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #11**

2016-11-07 15:39

MOT test number

730736198354

Result**✓ Passed****Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2016-11-07 11:27**MOT test number** 152258402393**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside rear brake binding (3.7.B.1)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #9** 2015-10-29 15:00**MOT test number** 793698428866**Result** ✓ Passed**MOT #8** 2015-10-29 13:35**MOT test number** 643800891917**Result** ✗ Failed**Fail** Offside Front Track rod end ball pin shank loose (2.2.B.1c)**MOT #7** 2014-10-21 11:44**MOT test number** 986594594212**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a pin/bearing (2.4.G.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6** 2014-10-21 10:30**MOT test number** 199404494266**Result** ✗ Failed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Track rod end ball pin shank loose (2.2.B.1c)**Advice** Offside Front Suspension arm has slight play in a pin/bearing (2.4.G.2)**MOT #5** 2013-10-23 11:26**MOT test number** 345966493223**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a pin/bearing (2.4.G.2)**MOT #4** 2013-10-23 11:26**MOT test number** 445186293255**Result** ✗ Failed**Advice** Offside Front Suspension arm has slight play in a pin/bearing (2.4.G.2)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #3** 2012-10-29 11:48**MOT test number** 425483402334**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #2** 2011-11-04 10:29**MOT test number** 848768701302**Result** ✓ Passed



MOT #1	2010-10-25 13:57
MOT test number	831868290232
Result	✓ Passed



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-11-10
Last registration	2021-12-02
Complete history	See info



Registration #1	2007-11-10	24 mi
Registration #2	2010-10-25	37.172 mi
Registration #3	2011-11-04	47.837 mi
Registration #4	2012-10-29	55.377 mi
Registration #5	2013-10-23	61.084 mi
Registration #6	2014-10-21	67.202 mi
Registration #7	2014-10-21	67.202 mi
Registration #8	2015-10-29	73.053 mi
Registration #9	2015-10-29	73.053 mi
Registration #10	2016-11-07	78.120 mi
Registration #11	2016-11-07	78.120 mi
Registration #12	2016-11-07	78.120 mi
Registration #13	2016-11-07	78.120 mi
Registration #14	2016-11-07	78.120 mi
Registration #15	2016-11-07	78.120 mi
Registration #16	2016-11-07	78.120 mi
Registration #17	2016-11-07	78.120 mi
Registration #18	2016-11-07	78.120 mi
Registration #19	2016-11-07	78.120 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1811 mm
Height	1445 mm
Length	4676 mm
Wheel base	2725 mm
Kerb weight	1580 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number

DYUK4028186