





report date: 2024-03-29

### General information

Make	KIA
Model	SORENTO CRDI KX-3 ISG
Colour	White
Year of manufacture	2017
Top speed	124 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	197 BHP
Max. torque	441 Nm at 1.750 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	42.8 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



LC17ONG
report date: 2024-03-29

### Internet history

#### Entry 3

Date 2022-02-10

Pictures 15

Listing price <u>View report</u>









#### source: cargurus.co.uk

#### Entry 2

[	Date	2022-02-09

Pictures 30

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-06-22
Date	2021-00-22

Pictures 32

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



LC170NG report date: 2024-03-29

MOT history

MOT expiry date	2024-05-15
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	4
Total items failed	3

MOT #6	2023-05-16 13:40
MOT test number	169185570068
Result	✓ Passed
Next expiry date	2024-05-15

MOT #5		2022-05-09 09:43
MOT test	number	362193290951
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge + edges low (5.2.3 (e))	)
Advice	Offside Front Tyre worn close to legal limit/worn on edge + edges low (5.2.3 (e))	

MOT #4	2021-07-01 12:05
MOT test number	422511712948
Result	✓ Passed

MOT #3	2020-08-27 11:12
MOT test number	185243032893
Result	✓ Passed

CarCheck.co.uk page 3/11



LC17ONG

report date: 2024-03-29

MOT #2 2020-08-20 14:57

**MOT test number** 407020468533

Result X Failed

**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #1** 2020-05-05 06:53

**MOT test number** 369414776320

Result \( \sqrt{Passed} \)

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



LC17ONG
report date: 2024-03-29

### Tax & MOT check



Tax status	Valid until 1 May
Days left	3
MOT expiry date	15 May 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	J
First licence fee (12 months)	£ 1.040,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.565,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



LC170NG report date: 2024-03-29

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



LC17ONG report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



LC170NG

report date: 2024-03-29

Owner	استحاجاتا
Owner	nistory
OVVIICI	IIIJCOI y

*	
For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



LC170NG report date: 2024-03-29

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 9/11



LC170NG

report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-05-13
Last registration	2023-05-16
Complete history	See info



Registration #1	2017-05-13	23 mi
Registration #2	2020-08-20	49.888 mi
Registration #3	2020-08-27	49.888 mi
Registration #4		11.777 es
Registration #5	2021-07-01	58.918 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



LC170NG

report date: 2024-03-29

## Car features

50225	Air conditionin
50295	
60482	
0501	
0566	
0567	
60569	

## Safety ratings

NCAP rating	****
Adult	90%
Children	83%
Pedestrian	67%
Safety systems	71%
Overall rating	80%
Video	see crash video



## Dimensions & weight

Width	1890 mm
Height	1685 mm
Length	4780 mm
Wheel base	2780 mm
Kerb weight	1953 kg
Max. allowed weight	2620 kg

# Additional information

Fuel tank capacity	71 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/1:

Number of axles 2

**Engine number** D4HBHH323154