



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 ZEST
Colour	Black
Year of manufacture	-
Top speed	98 mph
0 - 60 mph	15.1 seconds
Gearbox	7 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	94 Nm at 2.700 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-09-07
Pictures	11
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-02
Pictures	11
Listing price	View report



source: [cargurus.co.uk](#)

**MOT history**

MOT #22	2021-09-15 12:48
MOT test number	158290218411
Result	✓ Passed
Next expiry date	2022-09-14
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Exhaust outer skin corroded.
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #21	2020-08-19 11:06
MOT test number	974094013960
Result	✓ Passed
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #20	2020-08-18 16:30
MOT test number	802868753810
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #19	2019-08-22 14:17
MOT test number	520442876903
Result	✓ Passed
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18**

2019-08-21 15:28

MOT test number

748409474278

Result**✗ Failed****Fail** Nearside Windscreen wiper does not clear the windscreen effectively Wiper too small (3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Spare wheel insecure in carrier (6.1.5 (b) (i))**MOT #17**

2018-08-22 16:21

MOT test number

997672321677

Result**✓ Passed****Advice** Wiring altered so rear washer motor powers front washer**Advice** Front Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear number plate bulb cover missing

**MOT #16**

2018-08-22 09:57

MOT test number

932965446880

Result**✗ Failed****Advice**

Wiring altered so rear washer motor powers front washer

Fail

Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Offside Front Track rod end modification unsafe (2.1.3 (f) (i))

Fail

Side repeater incorrect colour both sides (4.4.3 (a))

Advice

Offside Rear number plate bulb cover missing

Fail

Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Front Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

MOT #15

2017-08-05 13:02

MOT test number

127341417093

Result**✓ Passed****MOT #14**

2017-07-28 08:05

MOT test number

322808013414

Result**✗ Failed****Fail**

Offside Front Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)

Fail

Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail

Nearside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail

Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #13** 2016-05-28 08:25**MOT test number** 779442049271**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #12** 2015-05-30 13:24**MOT test number** 557330355134**Result** ✓ Passed**MOT #11** 2015-05-30 09:37**MOT test number** 865280455157**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #10** 2014-05-31 14:28**MOT test number** 855921254164**Result** ✓ Passed**MOT #9** 2014-05-31 11:21**MOT test number** 808301054186**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #8**

2013-03-09 11:08

MOT test number

109138563006

Result

✓ Passed

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #7**

2011-11-19 11:59

MOT test number

687213121340

Result

✓ Passed

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** O/s/f wiper blade smearing screen slightly**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear bumper insecure**MOT #6**

2011-11-19 11:59

MOT test number

335343421307

Result

✗ Failed

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** O/s/f wiper blade smearing screen slightly**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear bumper insecure**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #5** 2010-11-12 12:59**MOT test number** 533426110337**Result** ✓ Passed**MOT #4** 2009-10-16 17:14**MOT test number** 993699289215**Result** ✓ Passed**Advice** Nearside Front Drag link end ball joint has slight play (2.2.B.1f)**MOT #3** 2008-12-18 12:42**MOT test number** 601313758361**Result** ✓ Passed**MOT #2** 2008-12-18 12:42**MOT test number** 872953558367**Result** ✗ Failed**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.5c)**MOT #1** 2007-12-12 15:36**MOT test number** 674846347373**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	RJ54BHK
Plate since	2024-03-28
Current registration	RJ54BHK
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-12-24
Last registration	2021-09-15
Complete history	See info



Registration #1	2004-12-24	14 mi
Registration #2	2007-12-12	24.048 mi
Registration #3	2008-12-18	31.370 mi
Registration #4	2009-10-16	35.196 mi
Registration #5	2010-11-12	44.167 mi
Registration #6	2011-11-19	46.131 mi
Registration #7	2013-03-09	48.775 mi
Registration #8	2014-05-31	52.413 mi
Registration #9	2014-05-31	52.413 mi
Registration #10	2015-05-30	55.589 mi
Registration #11	2015-05-30	55.589 mi
Registration #12	2016-05-28	57.777 mi
Registration #13	2016-05-28	57.777 mi
Registration #14	2016-05-28	57.777 mi
Registration #15	2016-05-28	57.777 mi
Registration #16	2016-05-28	57.777 mi
Registration #17	2016-05-28	57.777 mi
Registration #18	2016-05-28	57.777 mi
Registration #19	2016-05-28	57.777 mi
Registration #20	2016-05-28	57.777 mi
Registration #21	2016-05-28	57.777 mi
Registration #22	2016-05-28	57.777 mi
Registration #23	2016-05-28	57.777 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	985 kg
Max. allowed weight	1405 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	5

Number of axles	2
Engine number	FP7N4595647