





report date: 2024-03-29

## General information

Make	HYUNDAI
Model	IX20 SE BLUE DRIVE
Colour	White
Year of manufacture	2016
Top speed	104 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 сс
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	50.4 mpg
CO2 emission	130 g/km
CO2 label	D



CarCheck.co.uk page 1/11



Internet history

### Entry 2

Date 2021-07-24

Pictures 25

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2021-07-22

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-09-09
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #7		2023-09-07 14:45
MOT test	number	554521989051
Result		✓ Passed
Next expi	ry date	2024-09-09
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #6			2023-09-07 14:45
MOT test	number		977014232887
Result			<b>×</b> Failed
Advice	Nearside Rear B	rake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt			
	h rectification	Nearside Windscreen wiper does not clear the windscre	een effectively (3.4 (b)
(ii))			
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))			

CarCheck.co.uk page 3/11



MJ66NNX

report date: 2024-03-29

MOT test number

Result

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2022-08-26 09:15 **MOT** test number 145666158004 Result × Failed Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Fail (5.2.3 (d) (i)) **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #3	2021-09-10 15:12
MOT test number	299266240972
Result	<b>✓</b> Passed
MOT #2	2020-12-09 15:37
MOT test number	743374562083
Result	✓ Passed

MOT #1	2019-11-18 11:28
MOT test number	117940359580
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/11



# Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	9 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	D
	-
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



_		
Owne	 	
	ΙСΤ	nrv
	 IJL	

e which misterly	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full in	
********	
***************************************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	NIE UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-12-12
Last registration	2023-09-07
Complete history	See info



Registration #1	2016-12-12	11 mi
Registration #2	2019-11-18	14.559 mi
Registration #3	2020-12-09	19.546 mi
Registration #4		11.777 es
Registration #5		91.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4120 mm
Wheel base	2615 mm
Kerb weight	1267 kg
Max. allowed weight	1710 kg

#### Additional information

Fuel tank capacity	50 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	1/11

Number of axles 2

**Engine number** G4FAFZ607182