



Mercedes-Benz

 **KRI2KEJ**


report date: 2024-03-28

General information

|                     |                                   |
|---------------------|-----------------------------------|
| Make                | MERCEDES-BENZ                     |
| Model               | VIANO CDI BLUEEFFICIENCY AMBIENTE |
| Colour              | Black                             |
| Year of manufacture | 2012                              |
| Top speed           | 113 mph                           |
| 0 - 100 km/h        | 13.5 seconds                      |
| 0 - 60 mph          | 11.1 seconds                      |
| Gearbox             | 5 speed automatic                 |

Engine & fuel consumption

|                         |                           |
|-------------------------|---------------------------|
| Power                   | 100 kW / 136 HP / 163 BHP |
| Max. torque             | 360 Nm at 1.600 rpm       |
| Engine capacity         | 2.143 cc                  |
| Cylinders               | 4                         |
| Fuel type               | Diesel                    |
| Consumption city        | 27.7 mpg                  |
| Consumption extra urban | 40.4 mpg                  |
| Consumption combined    | 34.5 mpg                  |
| CO2 emission            | 214 g/km                  |
| CO2 label               | K                         |






Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-08-13                  |
| Pictures      | 8                           |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-08-14 |
| MOT pass rate      | 77 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 3          |
| Total advice items | 7          |
| Total items failed | 7          |

|                  |                  |
|------------------|------------------|
| MOT #13          | 2023-08-15 11:15 |
| MOT test number  | 400858518861     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-08-14       |

|                 |                  |
|-----------------|------------------|
| MOT #12         | 2022-08-03 10:15 |
| MOT test number | 957922922441     |
| Result          | ✓ Passed         |

|                 |                  |
|-----------------|------------------|
| MOT #11         | 2022-08-02 11:28 |
| MOT test number | 688738623267     |
| Result          | ✗ Failed         |

**Fail** Nearside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Sidewall (5.2.3 (d) (i))

|                 |                  |
|-----------------|------------------|
| MOT #10         | 2021-08-09 17:14 |
| MOT test number | 169835255109     |
| Result          | ✓ Passed         |

**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

|                 |                  |
|-----------------|------------------|
| MOT #9          | 2019-10-11 09:36 |
| MOT test number | 389793071588     |
| Result          | ✓ Passed         |

**MOT #8** 2019-10-11 09:16**MOT test number** 196156443513**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**MOT #7** 2018-10-01 12:05**MOT test number** 306684351095**Result** ✓ Passed**Advice** Both wipers slightly worn**Advice** Nearside Rear tyre worn/on the legal limit**MOT #6** 2017-05-09 15:23**MOT test number** 854235097632**Result** ✓ Passed**MOT #5** 2016-02-13 12:00**MOT test number** 521861321504**Result** ✓ Passed**MOT #4** 2016-02-11 17:33**MOT test number** 769905747035**Result** ✗ Failed**Fail** Offside Rear Wheel bolt(s) missing (4.2.A.1e)**Fail** Nearside Side repeater excessively deteriorated so that it is not visible from a reasonable distance (1.4.A.2e)**Fail** Offside Front Wheel bolt(s) missing (4.2.A.1e)**Fail** Nearside Rear Wheel bolt(s) missing (4.2.A.1e)

**MOT #3** 2015-02-04 17:39**MOT test number** 756855235088**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2015-01-05 15:00**MOT test number** 227175205096**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2014-01-04 14:56**MOT test number** 487574904022**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
14 August 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 February          |
| <b>Days left</b>        | 278                             |
| <b>MOT expiry date</b>  | 14 August 2024                  |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | K          |
| <b>Single payment (12 months)</b>              | £ 395,00,- |
| <b>Single six month payment</b>                | £ 217,25,- |
| <b>Total payable by 12 monthly instalments</b> | £ 414,75,- |



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >





Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |      |
|-------|------|
| Owner | From |
| Owner | From |
| Owner | From |
| Owner | From |
| Owner | From |
| Owner | From |
| Owner | From |

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

|                      |  |
|----------------------|--|
| Number of plates     | 1  |
| Current registration |  <b>KR12KEJ</b> |
| Plate since          | 2019-03-28   |
| Current registration |  <b>KR12KEJ</b> |
| Plate since          | 2019-03-28   |

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 15                       |
| First mileage registration | 2012-07-25               |
| Last registration          | 2023-08-15               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2012-07-25 | 11 mi     |
| Registration #2  | 2014-01-04 | 9.144 mi  |
| Registration #3  | 2015-01-05 | 26.184 mi |
| Registration #4  | 2015-02-04 | 26.710 mi |
| Registration #5  | 2016-02-11 | 42.432 mi |
| Registration #6  | 2016-02-13 | 42.436 mi |
| Registration #7  | 2017-05-09 | 55.974 mi |
| Registration #8  | 2018-10-01 | 69.074 mi |
| Registration #9  | 2019-05-20 | 75.377 mi |
| Registration #10 | 2019-05-20 | 75.377 mi |
| Registration #11 | 2019-05-20 | 75.377 mi |
| Registration #12 | 2019-05-20 | 75.377 mi |
| Registration #13 | 2019-05-20 | 75.377 mi |
| Registration #14 | 2019-05-20 | 75.377 mi |
| Registration #15 | 2019-05-20 | 75.377 mi |

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

|             |         |
|-------------|---------|
| Width       | 1901 mm |
| Height      | 1875 mm |
| Length      | 4763 mm |
| Wheel base  | 3200 mm |
| Kerb weight | 2166 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 75 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 8                |

**Number of axles**

2

**Engine number**

65194031164111