



**BG56WUV**

report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | AUDI           |
| Model               | A6 TDI DPF SE  |
| Colour              | Silver         |
| Year of manufacture | 2006           |
| Top speed           | 130 mph        |
| 0 - 60 mph          | 10.5 seconds   |
| Gearbox             | 6 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 140 BHP             |
| Max. torque             | 320 Nm at 1.750 rpm |
| Engine capacity         | 1.968 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 32.1 mpg            |
| Consumption extra urban | 56.5 mpg            |
| Consumption combined    | 44.1 mpg            |
| CO2 emission            | 163 g/km            |
| CO2 label               | G                   |







Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-06-09                  |
| Pictures      | 11                          |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-01-17 |
| MOT pass rate      | 70 %       |
| MOT passed         | 14         |
| Failed MOT tests   | 6          |
| Total advice items | 31         |
| Total items failed | 16         |

|                  |   |
|------------------|---|
| MOT #20          | 2023-01-18 14:27  |
| MOT test number  | 393253892824  |
| Result           | ✓ Passed  |
| Next expiry date | 2024-01-17  |
| Advice           | Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))   |
| Advice           | Tyre worn close to legal limit/worn on edge both rear (5.2.3 (e))   |
| Advice           | Oil leak, but not excessive (8.4.1 (a) (i))   |
| Minor            | Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Advice           | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))                                       |
| Advice           | Front Brake pad(s) wearing thin (1.1.13 (a) (ii))   |

|                 |  |
|-----------------|--|
| MOT #19         | 2021-11-20 13:31   |
| MOT test number | 742393224617   |
| Result          | ✓ Passed   |
| Advice          | Oil leak, but not excessive (8.4.1 (a) (i))  |
| Advice          | Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))                                      |
| Advice          | Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))                                       |
| Advice          | Front Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i)) |
| Advice          | Offside Front Shock absorbers has light misting of oil (5.3.2 (b))                                       |

**MOT #18**

2021-11-19 17:39

**MOT test number**

552839027812

**Result****✗ Failed**

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Offside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Nearside Rear Inner Tyre has ply or cords damaged (5.2.3 (d) (ii))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

**MOT #17**

2020-11-19 16:06

**MOT test number**

212424560596

**Result****✓ Passed**

- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #16** 2020-11-19 10:00**MOT test number** 257791597695**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**MOT #15** 2019-11-11 16:11**MOT test number** 667945094154**Result** ✓ Passed**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #14** 2019-11-11 10:27**MOT test number** 290120102816**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #13** 2018-11-14 11:52**MOT test number** 291808286321**Result** ✓ Passed**MOT #12** 2018-11-12 15:41**MOT test number** 279169238142**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #11** 2017-11-09 14:50**MOT test number** 148479243833**Result** ✓ Passed**MOT #10** 2016-10-24 14:36**MOT test number** 323847882881**Result** ✓ Passed**MOT #9** 2016-10-24 08:43**MOT test number** 111089641087**Result** ✗ Failed**Fail** Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)**MOT #8** 2015-10-13 10:43**MOT test number** 440051517571**Result** ✓ Passed**Advice** Offside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #7** 2015-10-08 13:07**MOT test number** 758001004917**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #6** 2014-10-14 12:54**MOT test number** 395367984466**Result** ✓ Passed**MOT #5** 2013-10-11 12:42**MOT test number** 548924783295**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-10-19 13:59**MOT test number** 505473692249**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-10-10 15:37**MOT test number** 338883681480**Result** ✓ Passed**MOT #2** 2010-10-18 09:16**MOT test number** 692351190293**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt



|                 |  |
|-----------------|--|
| MOT #1          | 2009-11-10 09:21   |
| MOT test number | 761154019307   |
| Result          | ✓ Passed   |
| Notice          | Child seat fitted not allowing full inspection of adult belt |
| Advice          | Offside Rear Tyre worn close to the legal limit (4.1.E.1)    |





Tax & MOT check

X

Untaxed

Tax expired:  
1 April 2023

X

MOT

Expired:  
17 January 2024

|                  |                                 |
|------------------|---------------------------------|
| Tax status       | Expired at 1 April 2023         |
| Days left        | 393 days too late               |
| MOT expiry date  | 17 January 2024                 |
| Full MOT history | <a href="#">See MOT history</a> |

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 49         |
| Band                                    | G          |
| Single payment (12 months)              | £ 240,00,- |
| Single six month payment                | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this AUDI had different number plates.

|                      |               |
|----------------------|---------------|
| Number of plates     | 1             |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2019-01-01    |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2019-01-01    |

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 22                       |
| First mileage registration | 2006-11-22               |
| Last registration          | 2023-01-18               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2006-11-22 | 26 mi      |
| Registration #2  | 2009-11-10 | 68.695 mi  |
| Registration #3  | 2010-10-18 | 84.514 mi  |
| Registration #4  | 2011-10-10 | 98.624 mi  |
| Registration #5  | 2012-10-19 | 109.856 mi |
| Registration #6  | 2013-10-11 | 120.182 mi |
| Registration #7  | 2014-10-14 | 131.070 mi |
| Registration #8  | 2015-10-08 | 142.902 mi |
| Registration #9  | 2015-10-13 | 143.081 mi |
| Registration #10 | 2016-10-24 | 151.953 mi |
| Registration #11 | 2016-10-24 | 151.953 mi |
| Registration #12 | 2016-10-24 | 151.953 mi |
| Registration #13 | 2016-10-24 | 151.953 mi |
| Registration #14 | 2016-10-24 | 151.953 mi |
| Registration #15 | 2016-10-24 | 151.953 mi |
| Registration #16 | 2016-10-24 | 151.953 mi |
| Registration #17 | 2016-10-24 | 151.953 mi |
| Registration #18 | 2016-10-24 | 151.953 mi |
| Registration #19 | 2016-10-24 | 151.953 mi |
| Registration #20 | 2016-10-24 | 151.953 mi |
| Registration #21 | 2016-10-24 | 151.953 mi |
| Registration #22 | 2016-10-24 | 151.953 mi |

More info >



Car features

The AUDI factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1855 mm |
| Height              | 1463 mm |
| Length              | 4933 mm |
| Wheel base          | 2843 mm |
| Kerb weight         | 1610 kg |
| Max. allowed weight | 2240 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 70 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |

|                        |            |
|------------------------|------------|
| <b>Number of axles</b> | 2          |
| <b>Engine number</b>   | BRE 070977 |