



report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 SE LUX AWD
Colour	Blue
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	235 BHP
Max. torque	320 Nm at 3.200 rpm
Engine capacity	3.192 cc
Cylinders	6
Fuel type	Petrol
Consumption city	16.8 mpg
Consumption extra urban	31.7 mpg
Consumption combined	23.9 mpg
CO2 emission	281 g/km
CO2 label	M






Internet history


Entry 1


Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



Highly Rated

FOR OUR  
CUSTOMER  
SERVICE 2020







**Click & Deliver**

Complete your deal online or by phone.  
Then arrange for the sanitised vehicle to be delivered to you.


Visit our website for more info.






£170.28 per month

ULEV REPRESENTATIVE EXAMPLE	
CASH PRICE	£1,790.00
DEPOSIT	£1,000.00
TOTAL AMOUNT OF CREDIT	£7,990.00
TOTAL AMOUNT PAYABLE	£11,774.00
ADMINISTRATION FEE	£140.00
OPTION TO PURCHASE FEE	£10.00
FIXED INTEREST RATE	4.50% P.A.
REPRESENTATIVE APR	11.40% APR
DURATION OF AGREEMENT	60 MONTHS
MONTHLY PAYMENT	£170.28
60 MONTHLY PAYMENTS	£10,216.80
FINAL PAYMENT	£1,557.20






WE HAVE

**37**

OTHER VOLVO XC90 IN STOCK

www.ulevsales.co.uk



source: autoonline.co.uk



## MOT history

MOT expiry date	2025-04-01
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	31
Total items failed	13

**MOT #23** 2024-04-02 15:10**MOT test number** 901182984510**Result** ✓ Passed**Next expiry date** 2025-04-01**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge reads 3.1mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge reads 3.2mm (5.2.3 (e))**MOT #22** 2024-04-02 09:01**MOT test number** 502012055103**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge reads 3.1mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge reads 3.2mm (5.2.3 (e))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #21** 2023-03-27 11:21**MOT test number** 968578235607**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Offside Front Play in steering rack inner joint(s)

**MOT #20** 2023-03-27 11:21**MOT test number** 627930796867**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Pass with rectification** Front Position lamp not working Both sides (4.2.1 (a) (ii))**Advice** Offside Front Play in steering rack inner joint(s)**MOT #19** 2022-03-28 10:52**MOT test number** 128358487752**Result** ✓ Passed**MOT #18** 2021-03-30 14:48**MOT test number** 317877411195**Result** ✓ Passed**MOT #17** 2021-03-30 14:48**MOT test number** 789691995849**Result** ✗ Failed**Pass with rectification** Fuel cap/sealing device ineffective (6.1.3 (b) (i))**MOT #16** 2020-06-02 09:09**MOT test number** 850771163415**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases down pipe (6.1.2 (a))**Minor** Headlamp lens slightly defective both side (4.1.1 (b) (i))



<b>MOT #15</b>	2019-03-22 17:03
<b>MOT test number</b>	295845428238
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Exhaust has a minor leak of exhaust gases down pipe (6.1.2 (a))

<b>MOT #14</b>	2019-03-21 12:14
<b>MOT test number</b>	197470257961
<b>Result</b>	✗ Failed
<b>Fail</b>	Parking brake efficiency below requirements (1.4.2 (a) (i))
<b>Fail</b>	Offside Rear Position lamp not working (4.2.1 (a))
<b>Advice</b>	Front Exhaust has a minor leak of exhaust gases down pipe (6.1.2 (a))
<b>Advice</b>	Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Fail</b>	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Advice</b>	Front Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))

<b>MOT #13</b>	2018-03-24 11:32
<b>MOT test number</b>	590202035611
<b>Result</b>	✓ Passed

<b>MOT #12</b>	2017-03-30 10:03
<b>MOT test number</b>	543361832412
<b>Result</b>	✓ Passed
<b>Advice</b>	Child Seat fitted not allowing full inspection of adult belt

<b>MOT #11</b>	2016-03-18 09:21
<b>MOT test number</b>	568282016334
<b>Result</b>	✓ Passed

**MOT #10** 2016-03-16 11:18**MOT test number** 873051854351**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**Advice** All four tyres deteriorated**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Rear tyre has a nail**MOT #9** 2015-03-20 14:48**MOT test number** 458329575008**Result** ✓ Passed**Notice** All four tyres low on edges and slight cracking**Notice** Play in steering rack inner joint(s)**MOT #8** 2015-03-20 11:02**MOT test number** 147419475437**Result** ✗ Failed**Notice** Play in steering rack inner joint(s)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Notice** All four tyres low on edges and slight cracking**Fail** Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**MOT #7** 2014-03-11 16:01**MOT test number** 426210174009**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Fuel cap seal cracked

**MOT #6** 2014-03-11 09:16**MOT test number** 127610674471**Result** ✗ Failed**Notice** Fuel cap seal cracked**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Front brake pads and discs worn low**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #5** 2013-03-16 16:12**MOT test number** 809115573096**Result** ✓ Passed**MOT #4** 2012-03-22 14:09**MOT test number** 577152082003**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-03-14 12:47**MOT test number** 367864172091**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #2** 2011-04-04 10:55**MOT test number** 697964591017**Result** ✓ Passed**Advice** Offside Front Ball joint has slight play (2.2.B.1f)



MOT #1	2009-10-07 10:27
MOT test number	650560189217
Result	✓ Passed
Advice	Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)
Notice	Advanced wear noted on front brake pads,replace as soon as possible.





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
1 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	1 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	M
<b>Single payment (12 months)</b>	£ 695,00,-
<b>Single six month payment</b>	£ 382,25,-
<b>Total payable by 12 monthly instalments</b>	£ 729,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2006-10-06
Last registration	2024-04-02
Complete history	<a href="#">See info</a>



Registration #1	2006-10-06	27 mi
Registration #2	2009-10-07	31.058 mi
Registration #3	2011-04-04	39.846 mi
Registration #4	2012-03-14	45.581 mi
Registration #5	2012-03-22	45.649 mi
Registration #6	2013-03-16	50.453 mi
Registration #7	2014-03-11	56.284 mi
Registration #8	2014-03-11	56.284 mi
Registration #9	2015-03-20	63.810 mi
Registration #10	2015-03-20	63.810 mi
Registration #11	2016-03-16	70.227 mi
Registration #12	2016-03-18	70.227 mi
Registration #13	2017-03-30	78.183 mi
Registration #14	2018-03-20	85.227 mi
Registration #15	2018-03-20	85.227 mi
Registration #16	2019-03-20	92.227 mi
Registration #17	2019-03-20	92.227 mi
Registration #18	2020-03-20	99.227 mi
Registration #19	2020-03-20	99.227 mi
Registration #20	2021-03-20	106.227 mi
Registration #21	2021-03-20	106.227 mi
Registration #22	2022-03-20	113.227 mi
Registration #23	2022-03-20	113.227 mi
Registration #24	2023-03-20	120.227 mi
Registration #25	2024-04-02	127.227 mi



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	2046 mm
Length	4798 mm
Wheel base	2857 mm
Kerb weight	2143 kg
Max. allowed weight	2760 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	170806B07313