



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK SLK 200 KOMPRESSOR
Colour	Red
Year of manufacture	2010
Top speed	147 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	36.2 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-12-23
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-12-21
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



## MOT history

MOT expiry date	2024-11-14
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	12
Total items failed	7

MOT #14	2023-11-15 12:07
MOT test number	380828408827
Result	✓ Passed
Next expiry date	2024-11-14
Advice	Front Exhaust mounting defective (6.1.2 (a))

MOT #13	2023-11-14 12:06
MOT test number	649550989540
Result	✗ Failed
Advice	Front Exhaust mounting defective (6.1.2 (a))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #12	2022-12-12 14:26
MOT test number	704570363937
Result	✓ Passed

**MOT #11** 2022-12-12 10:39**MOT test number** 438679663059**Result** ✗ Failed

- Fail** Windscreen in an unacceptable condition (3.2 (c) (i))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Windscreen washer not working (3.5 (a))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #10** 2022-01-07 12:53**MOT test number** 282564508855**Result** ✓ Passed**MOT #9** 2021-03-13 10:04**MOT test number** 676319602301**Result** ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #8** 2020-02-28 09:24**MOT test number** 834566578789**Result** ✓ Passed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #7** 2019-02-26 09:20**MOT test number** 845604911660**Result** ✓ Passed

- Advice** Front number plate damaged

**MOT #6** 2018-02-08 09:19**MOT test number** 850327648917**Result** ✓ Passed**Advice** Front number plate damaged**MOT #5** 2017-02-16 17:40**MOT test number** 629460081549**Result** ✓ Passed**MOT #4** 2017-02-16 11:06**MOT test number** 530765831378**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2016-02-24 10:08**MOT test number** 622756809012**Result** ✓ Passed**Advice** Under trays fitted to vehicle**MOT #2** 2015-01-30 09:13**MOT test number** 116030135080**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components



MOT #1	2013-08-29 10:41
MOT test number	905901443296
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
14 November 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	14 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-08-27
Last registration	2023-11-15
Complete history	<a href="#">See info</a>



Registration #1	2010-08-27	25 mi
Registration #2	2013-08-29	18.735 mi
Registration #3	2015-01-30	29.811 mi
Registration #4	2016-02-24	36.235 mi
Registration #5	2017-02-16	41.313 mi
Registration #6	2017-02-16	41.313 mi
Registration #7	2018-02-08	45.746 mi
Registration #8	2019-02-26	53.154 mi
Registration #9	2020-02-28	56.508 mi
Registration #10	2020-05-20	58.277 mi
Registration #11	2020-05-20	58.277 mi
Registration #12	2020-05-20	58.277 mi
Registration #13	2020-05-20	58.277 mi
Registration #14	2020-05-20	58.277 mi
Registration #15	2020-05-20	58.277 mi
Registration #16	2020-05-20	58.277 mi
Registration #17	2020-05-20	58.277 mi

More info >



Dimensions & weight

Width	2012 mm
Height	1296 mm
Length	4103 mm
Wheel base	2430 mm
Kerb weight	1390 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27195431311467